5/27/22, 12:04 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI22004341/KVCN2

27/05/2022 Date:

REFERENCE

Colour:

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: MN000206

Claimant Vehicle No:

SHD9358T

Insured Vehicle No: **SLP5628E**

Date of Loss: 23/04/2022 Nature of Claim: TP

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHD9358T**

Make & Model: TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)

Metallic Pearl White/Red

2ZR2C37186 Engine No:

Reg. Date: 27/06/2019 (Man. Year: 2018)

Odometer:

Chassis No:

232192 km

JTDKB3FU803082136

Claim No:

M2202274

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: Pre-accident Condition: No

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15 Front Left Side: Rear Left Side: Firenza 7 mm Sailun 6 mm Front Right Side: Firenza 7 mm Rear Right Side: Sailun 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,408.27	2,651.37	5,756.90	68.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,590.00	785.00	2,805.00	78.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$	11,998.27	3,436.37	8,561.90	71.36
Approved Total (Overridden) (S\$)	2,750.00		
(S\$	11,998.27	2,750.00	9,248.27	77.08
+ GST 7.00/7.00% (S\$	839.88	192.50	647.38	77.08
Nett Amount (S\$	12,838.15	2,942.50	9,895.65	77.08

INSPECTION

Date of Assignment: 10/05/2022

Trans-cab Auto Services Pte Ltd (Ang Mo Kio) Date Inspected: 09/05/2022 Inspected At:

2, Ang Mo Kio Street 63

Singapore 569111

Estimated Period of Repair: 2.0 days

Adjuster: **KENNETH KONG** Manager: **VERON CHEN**

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 27 May 2022)

Parts: 144 TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List) **Print Code:** (Unsubmitted, no print-code for SHD9358T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*COVER,FRONT BUMPER	Buckled	516.00 FL	-	*516.00 FI
2	1		*ABSORBER,FRONT BUMPER ENERGY	Serviceable	79.60 FL	-	*- Fl
3	1		*REINFORCEMENT SUB-ASSY,FRONT BUMPER	Repair	716.60 FL	-	*- Fl
4	1		*STAY SUB-ASSY,FRONT BUMPER,RH	Serviceable	47.50 FL	-	*- Fl
5	1		*BRACKET,FRONT BUMPER SIDE,RH	Serviceable	59.30 FL	-	*- Fl
6	1		*LAMP ASSY,FOG RH	Serviceable	951.40 FL	-	*- Fl
7	1		*UNIT ASSY,HEADLAMP,RH	Serviceable	2,637.60 FL	-	*- Fl
8	1		*JAR ASSY,WINDSHIELD WASHER	Serviceable	219.10 FL	-	*- Fl
9	1		*MIRROR ASSY,OUTER REAR VIEW,RH	Serviceable	1,436.60 FL	-	*- FI
10	1		*RIM	Dented	1,900.10 FL	-	*1,900.10 FI
11	1		*MOULDING ASSY,BODY ROCKER PANEL,RH	Serviceable	594.80 FL	-	*- FI
12	1		*FENDER SUB-ASSY,FRONT RH	Bent	977.80 FL	-	*977.80 FI
13	1		*EMBLEM,SIDE PANEL RH	Necessary	54.60 FL	-	*54.60 FI
14	1		*LINER,FRONT FENDER RH	Serviceable	206.70 FL	-	*- Fl
15	1		*FRT BUMPER CLIP	Necessary	65.00 FS	-	*65.00 F
16	1		*TYRE	Serviceable	350.00 FS	-	*- F\$
17	1		*FENDER CLIP	Not Necessary	65.00 FS	-	*- F\$
18	1		*FENDER LINER CLIP	Not Necessary	65.00 FS	-	*- F\$
19	1		*FRT LH BUMPER RETAINER CLIP	Not Necessary	65.00 FS	-	*- F\$
F=Fra	ınchise	part. S=Spc	Nett. L=ListItemDisc.				
				Sub Total (S\$)	11,007.70	3,513.50	
			- List Item Discount on L Items 2	5.00/25.00% (S\$)	2,599.43	862.13	
				Total Parts (S\$)	8,408.27		2,651.37

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	0.00
2	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	1,400.00	300.00
3	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,400.00	440.00
4	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	30.00
5	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	15.00
	Gross Labour Cos		3,590.00	785.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >