

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22004344/APA3Q2**Date:** 08/09/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210082693
Claimant Vehicle No :	SMC4157K	Insured Vehicle No :	SNB1609L
Date of Loss:	07/05/2022	Nature of Claim:	TP
		Claim No:	5144778671SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMC4157K		
Make & Model:	HONDA VEZEL, 1.5 X CVT (A)	Engine No:	L15B5553542
Reg. Date:	29/06/2018 (Man. Year: 2018)	Chassis No:	RU11303534
Colour:	White	Odometer:	49881 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,437.92	5,680.96	2,756.96	32.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,380.00	2,060.00	1,320.00	39.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,817.92	7,740.96	4,076.96	34.50
Approved Total (Overridden) (S\$)		6,200.00		
(S\$)	11,817.92	6,200.00	5,617.92	47.54
+ GST 7.00/7.00% (S\$)	827.25	434.00	393.25	47.54
Nett Amount (S\$)	12,645.17	6,634.00	6,011.17	47.54
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
Nett Liability (S\$)		6,994.00		

INSPECTION

Date of Assignment:	17/05/2022	
Date Inspected:	17/05/2022	Inspected At: Modern Automotive Pte Ltd (HQ) Blk 3023A Ubi Road 1, #01-61 & #01-58 Singapore 408717
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE LAMP	Not Necessary	77.00 FL	*- FL
2	1		*REAR BUMPER	Distorted	765.40 FL	*765.40 FL
3	2		*REAR BUMPER SIDE HOLDER -LH & RH	Necessary	57.00 FL	*57.00 FL
4	2		*REAR BUMPER REFLECTOR -LH & RH	Not Necessary	282.20 FL	*- FL
5	2		*REAR CORNER BUMPER -LH & RH	Repair	390.00 FL	*- FL
6	1		*REAR END PANEL	Distorted	585.40 FL	*585.40 FL
7	1		*REAR END PANEL TOP GARNISH	Deformed	98.40 FL	*98.40 FL
8	1		*REAR END PANEL ANTENNA SENSOR	Not Necessary	85.20 FL	*- FL
9	1		*REAR END PANEL BUZZER	Damaged	125.50 FL	*125.50 FL
10	1		*TAILLAMP -LH & RH	N/S Cut	949.20 FL	*474.60 FL
11	1		*TAILGATE	Distorted	1,100.00 FL	*1,100.00 FL
12	1		*TAILGATE LOCK	Damaged	182.50 FL	*182.50 FL
13	1		*TAILGATE WEATHERSTRIPE	Cut	186.40 FL	*186.40 FL
14	2		*TAILGATE REFLECTOR -LH & RH	Cracked	826.40 FL	*826.40 FL
15	2		*TAILGATE REFLECTOR SPONGE GASKET-LH & RH	Necessary	40.00 FL	*40.00 FL
16	1		*TAILGATE INNER TRIMBOARD	Deformed	285.60 FL	*285.60 FL
17	1		*TAILGATE OUTER GARNISH	Not Necessary	325.40 FL	*- FL
18	2		*TAILGATE DAMPER -LH & RH	Not Necessary	365.40 FL	*- FL
19	1		*TAILGATE GLASS MOULDING	Necessary	145.00 FL	*145.00 FL
20	1		*HONDA LOGO	Not Necessary	30.40 FL	*- FL
21	1		*VEZEL EMBLEM	Necessary	45.90 FL	*45.90 FL
22	1		*SPARE TYRE PANEL TOP COVER	Deformed	306.60 FL	*306.60 FL
23	1		*SPARE TYRE PANEL UNDERCOVER	Deformed	268.20 FL	*268.20 FL
24	1		*TOOLS TRAY SPONGE	Cracked	285.40 FL	*285.40 FL
25	2		*REAR FENDER INNER TRIMBOARD -LH & RH	Deformed	610.40 FL	*610.40 FL
26	1		*REAR EXHAUST PIPE	Not Necessary	598.60 FL	*- FL
27	1		*REAR EXHAUST PIPE MOUNTING	Not Necessary	32.40 FL	*- FL
28	1		*REAR EXHAUST PIPE GASKET	Not Necessary	35.00 FL	*- FL
29	1		*REAR NUMBER PLATE	Bent	30.00 FS	*30.00 FS
30	1		*REAR NUMBER PLATE HOLDER	Deformed	30.00 FS	*30.00 FS
31	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
32	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
33	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
34	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
35	1		*TAILLAMP SPONGE GASKET -LH & RH	N/S Necessary	40.00 FS	*20.00 FS
36	1		*SET TAILLAMP INNER TRIMBOARD CLIPS	Necessary	30.00 FS	*30.00 FS
37	1		*SET TAILGATE OUTER GARNISH CLIPS	Not Necessary	20.00 FS	*- FS
38	1		*TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
39	1		*REAR CAMERA	Not Necessary	480.00 FS	*- FS
40	1		*SET SPARE TYRE PANEL UNDERCOVER CLIPS	Necessary	30.00 FS	*30.00 FS
41	2		*SET REAR FENDER INNER TRIMBOARD CLIPS	Necessary	60.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,254.90	6,958.70
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,816.98	1,277.74
Total Parts (\$\$)	8,437.92	5,680.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCKING & PULL OUT REAR PORTION & RENEW ABOVE PARTS	New	1,200.00	800.00
2	TO PUTTY & SPRAY UP PAINT WORKS	New	1,200.00	800.00
3	TO CHECK WIRING	New	50.00	30.00
4	TO REMOVE REVERSE SENSOR	New	100.00	50.00
5	TO REMOVE REAR CAMERA	New	100.00	50.00
6	TO REMOVE VIDEO CAMERA	New	100.00	50.00
7	TO REMOVE UPHOLSTERY	New	150.00	80.00
8	TO TRANSFER TAILGATE FITTINGS	New	150.00	80.00
9	TO REMOVE TAILGATE GLASS	New	180.00	120.00
10	TO REMOVE EXHAUST PIPE	New	150.00	0.00
Gross Labour Cost (\$\$)			3,380.00	2,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >