

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22004345/UPA3Q2**Date:** 27/07/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900093298
Claimant Vehicle No :	SBL75Y	Insured Vehicle No :	SMG230L
Date of Loss:	09/05/2022	Nature of Claim:	TP
		Claim No:	6196797353SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBL75Y	Engine No:	L15B4030773
Make & Model:	HONDA VEZEL, 1.5 X CVT (A)	Chassis No:	RU11110770
Reg. Date:	24/05/2016 (Man. Year: 2015)	Odometer:	113312 km
Colour:	Maroon		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,088.70	10,892.64	10,196.06	48.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,040.00	4,210.00	1,830.00	30.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	27,128.70	15,102.64	12,026.06	44.33
Approved Total (Overridden) (S\$)		12,000.00		
(S\$)	27,128.70	12,000.00	15,128.70	55.77
+ GST 7.00/7.00% (S\$)	1,899.01	840.00	1,059.01	55.77
Nett Amount (S\$)	29,027.71	12,840.00	16,187.71	55.77
+ Loss of Use (13.0 x S\$60.00/day) (S\$)		780.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		13,622.00		
Global Sum Settlement (S\$)		13,600.00		

INSPECTION

Date of Assignment:	10/05/2022	
Date Inspected:	10/05/2022	Inspected At: Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	12.0 days	

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

SPECIAL REMARKS

Market Value: \$53,000.00 (est) less LTA Rebate: \$25,898.00 (est) = Nett Value
:\$27,102.00 (est)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	110.20 F	*110.20 FL
2	1		*TAILGATE	Badly Dented	1,099.20 F	*997.30 FL
3	1		*TAILGATE VEZEL EMBLEM	Necessary	66.80 F	*66.80 FL
4	1		*TAILGATE H LOGO	Necessary	45.00 F	*45.00 FL
5	1		*TAILGATE OUTER HANDLE GARNISH	Cracked	450.00 F	*312.00 FL
6	2		*TAILGATE REFLECTORS	Cracked	772.40 F	*610.20 FL
7	1		*TAILGATE INNER LOCK	Bent	199.80 F	*180.20 FL
8	1		*TAILGATE LOCK STRIKER	Not Necessary	66.00 F	*- FL
9	1		*TAILGATE INNER TRIM BOARD	Distorted	435.00 F	*288.50 FL
10	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 F	*50.00 FL
11	1		*TAILGATE REAR WIPER MOTOR	Serviceable	645.20 F	*- FL
12	1		*TAILGATE WEATHERSTRIP	Twisted	288.00 F	*162.30 FL
13	1		*REAR BUMPER	Distorted	980.00 F	*762.30 FL
14	2		*REAR BUMPER SIDES	Distorted / Warped	470.20 F	*470.20 FL
15	1		*REAR BUMPER REFLECTORS	O/S Broken	302.00 F	*151.00 FL
16	1		*REAR BUMPER UNDER COVER	Distorted	541.00 F	*311.30 FL
17	1		*SET REAR BUMPER UNDER COVER CLIPS	Necessary	50.00 F	*50.00 FL
18	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
19	1		*REAR END PANEL	Badly Dented	665.20 F	*517.30 FL
20	1		*REAR END PANEL TOP GARNISH	Distorted	341.10 F	*122.60 FL
21	2		*TAILLAMPS	Cracked	1,300.00 F	*964.00 FL
22	1		*TAILLAMP HOUSING PANELS	N/S Repair / O/S Dented	700.00 F	*285.00 FL
23	1		*REAR BUZZLE SENSOR	Cracked	98.00 F	*98.00 FL
24	1		*REAR ANTENNA SENSOR	Cracked	188.20 F	*188.20 FL
25	1		*REAR FENDERS	N/S Repair / O/S Buckled	2,180.00 F	*971.10 FL
26	2		*REAR FENDER OUTER PROTECTORS	Torn / Distorted	760.00 F	*490.00 FL
27	2		*REAR FENDER INNER TRIM BOARDS	Deformed / Distorted	790.00 F	*762.00 FL
28	1		*REAR FENDER UNDER TRIM O/S	Torn	336.00 F	*186.50 FL
29	1		*REAR WHEEL HOUSING PANEL O/S	Repair	909.20 F	*- FL
30	1		*REAR FLOOR PANEL	Crumpled / Buckled	1,280.00 F	*1,025.30 FL
31	1		*REAR FLOOR PANEL SIDE PANEL O/S	Bent	455.00 F	*211.50 FL
32	1		*REAR FLOOR PANEL TOP BOARD	Warped	522.00 F	*316.00 FL
33	1		*REAR FLOOR PANEL TOOLS SPONGE	Torn	785.00 F	*450.50 FL
34	2		*REAR EXHAUST MOUNTINGS	Torn	120.00 F	*120.00 FL
35	1		*REAR EXHAUST	Bent	765.00 F	*645.00 FL
36	1		*CENTRE EXHAUST PIPE	Bent	1,055.20 F	*1,015.00 FL
37	1		*REAR EXHAUST HEAT SHIELD	Bent	168.00 F	*168.00 FL
38	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
39	1		*REAR WINDSCREEN INNER SEAL	Necessary	50.00 FS	*40.00 FS
40	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
41	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
42	1		*SET REAR REVERSE CAMERA	Not Necessary	450.00 FS	*- FS
43	1		*SET REAR FLOOR PANEL INSULATOR	Not fitted	120.00 FS	*- FS
44	1		*REAR LICENCE PLATE	Cracked	50.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	21,088.70	13,523.30
- List Item Discount on L Items 0.00/20.00% (\$)	0.00	2,630.66
Total Parts (\$)	21,088.70	10,892.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	30.00
2	TO DISMANTLE & REPLACED REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	120.00
4	TO TRANSFER TAILGATE MECHANISM	New	100.00	60.00
5	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	80.00
6	TO RESET & REPROGRAMME DIAGNOSIS SYSTEM	New	180.00	50.00
7	TO DISMANTLE & REFIX REAR EXHAUST	New	180.00	100.00
8	TO SPRAY RUSTPROFING	New	100.00	100.00
9	TO DISMANTLE & REFIX REAR UNDER CARRIAGE	New	280.00	0.00
10	TO CONDUCT WHEEL ALIGNMENT	New	100.00	60.00
11	TO DISMANTLE & REFIX FUEL TANK	New	100.00	60.00
12	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	2,800.00	2,200.00
13	TO PUTTY & SPRAY PAINTING	New	1,800.00	1,300.00
Gross Labour Cost (\$\$)			6,040.00	4,210.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >