

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 3099X

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR LH FENDER PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	1,636.00	-
1	REAR LH CENTER PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	1,659.10	-
1	REAR LH WHEEL INNER SHIELD (CONSISTENT)	SERVICEABLE	49.00	-
1	REAR LH MUDFLAP (CONSISTENT)	SERVICEABLE	68.00	-
1	REAR LH SHOCK ABSORBER (CONSISTENT)	BENT	115.00	115.00
1	REAR LH SHOCK ABSORBER STOPPER (CONSISTENT)	SERVICEABLE	91.30	-
1	REAR LH BEARING WITH HUB (CONSISTENT)	BENT	381.30	351.60
1	REAR AXLE BEAM (CONSISTENT)	SERVICEABLE	2,417.10	-
1	REAR LH TYRE WHEEL HUB COVER (CONSISTENT)	DENTED	155.00	155.00
1	REAR BUMPER (CONSISTENT)	DENTED	485.90	485.90
	LESS 10% DISCOUNT		-705.77	-110.75
			6,351.93	996.75
	SPECIAL NETT ITEMS			
1	SET REAR LH WHEEL INNER SHIELD CLIPS (SN) (CONSISTENT)	NOT NECESSARY	20.00	-
1	REAR LH TYRE RIM (SN) (CONSISTENT)	SERVICEABLE	237.00	-
			257.00	-
	<u>LABOUR</u>			
	WHEEL ALIGNMENT.		100.00	60.00
	ANTI RUST.	NOT NECESSARY	250.00	-
	TO RESPRAY PAINTING & ETC.		1,200.00	400.00
	PANEL BEAT ,REMOVE AND REPLACING ABOVE PARTS.INCLUSIVE OF THE REPAIR OF REAR LH FENDER PANEL AND REAR LH CENTER PANEL .		2,200.00	400.00
			3,750.00	860.00
	GRAND TOTAL		10,358.93	1,856.75

Report Ref No. CC4/ASM22004346/Kpa3q2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		1,450.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC4/ASM22004346/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser