

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22004352/RNY3Q2**Date:** 01/12/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	SNM22D202847/C02/TAYHP
Claimant Vehicle No :	SMX9331E	Insured Vehicle No :	SJD8849B
Date of Loss:	26/04/2022	Nature of Claim:	TP
		Claim No:	SNM22D202847/C02/TAYHP

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMX9331E	Engine No:	1KRK035924
Make & Model:	TOYOTA RAIZE, 1.0 X CVT (A)	Chassis No:	A200A0030265
Reg. Date:	05/02/2021 (Man. Year: 2020)	Odometer:	15178 km
Colour:	Blue		
Engine Capacity:	996 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Average

CONDITION OF TYRES

Front Tyre Size:	195/55 R16	Rear Tyre Size:	195/55 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,095.00	1,270.00	825.00	39.38
Miscellaneous Items	35.00	0.00	35.00	100.00
Labour	1,125.60	403.20	722.40	64.18
Paintwork Labour	575.21	538.49	36.72	6.38
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	3,830.81	2,211.69	1,619.12	42.27
+ GST 7.00/7.00% (\$\$)	268.16	154.82	113.34	42.27
Nett Amount (\$\$)	4,098.97	2,366.51	1,732.46	42.27

INSPECTION

Date of Assignment:	10/05/2022	Present Location:	Auto Insure Pte Ltd (HQ) (Woodlands)
Date Inspected:	10/05/2022	Inspected At:	Auto Insure Pte Ltd (HQ) (Woodlands) 6 Marsiling Lane Singapore 739145
Estimated Period of Repair:	5.0 days		

Adjuster: MOHD RASUL**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Dec 2022)
Parts:	144	TOYOTA RAIZE 1.0 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMX9331E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PARTS		2,095.00 F	*1,270.00 F
F=Franchise part.						
Total Parts (\$\$)					2,095.00	1,270.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	EXTRAS	35.00	0.00
Sub Total (\$\$)			35.00	0.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	LABOUR FOR SPRAY PAINTING	New	575.21	538.49
<u>Labour Items</u>				
2	LABOUR FOR PANEL BEATING	New	1,125.60	403.20
Gross Labour Cost (\$\$)			1,700.81	941.69

Report was unsubmitted during this print-out.

< END OF ESTIMATES >