

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22004359/UVY3N2**Date:** 21/06/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNW00003832100

**Claimant Vehicle No :** SMM5479Y **Insured Vehicle No :** SMW4350M

Date of Loss: 08/05/2022 Nature of Claim: TP Claim No: SNM22D203184/C02/TANKW

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SMM5479Y**

Make & Model: KIA CERATO, 1.6 SX (A) Engine No: G4FGKH743019

Reg. Date: 03/07/2019 (Man. Year: 2019) Chassis No: KNAF3416MK5049435

Colour: Grey Odometer: 198570 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 225/45R17 Rear Tyre Size: 225/45R17

Front Left Side: Triangle 6 mm Rear Left Side: Triangle 6 mm

Front Right Side: Triangle 6 mm Rear Right Side: Triangle 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,541.00	0.00	1,541.00	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,020.00	1,440.00	2,580.00	64.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>5,561.00</b>	<b>1,440.00</b>	<b>4,121.00</b>	<b>74.11</b>
<b>+ GST 7.00/7.00% (S\$)</b>	389.27	100.80	288.47	74.11
<b>Nett Amount (S\$)</b>	<b>5,950.27</b>	<b>1,540.80</b>	<b>4,409.47</b>	<b>74.11</b>

**INSPECTION**

Date of Assignment: 10/05/2022

Date Inspected: 12/05/2022 Inspected At: Cycle & Carriage Fulco Motor Dealer Pte Ltd (HQ)  
330 Ubi Road 3  
Singapore 408650

Estimated Period of Repair: 2.0 days

**Adjuster:** MARCUS CHUA**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 21 Jun 2022)
<b>Parts:</b>	143	KIA CERATO 1.6 SX (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMM5479Y)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH REAR DOOR PANEL A	Repair	1,445.00 FS	*- FS
2	1		*W/STRIP ASSY RR DR B	Not Necessary	75.00 FS	*- FS
3	1		*BLACK TAPE-RR DR FR	Not Necessary	13.00 FS	*- FS
4	1		*BLACK TAPE-RR DR FRA	Not Necessary	8.00 FS	*- FS
<b>Total Parts (S\$)</b>					<b>1,541.00</b>	<b>0.00</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	DIAGNOSTIC / SCANNING	New	250.00	250.00
2	TO REPLACE RHR DOOR PANEL,ETC-TO REPAIR RHS SIDE SILL,STRAIGHTEN,REFORM,ALIGN ON RHS ACCIDENT AFFECTED AREAS }	New	1,280.00	640.00
3	TO TRANSFER RHR DOOR COMPONENTS AND MECHANISMS PARTS }	New	640.00	0.00
4	TO APPLY SEALANT KIT ON NEW PANEL	New	200.00	0.00
5	SPRAY PAINTING ON RHS ACCIDENT AFFECTED AREAS	New	1,650.00	550.00
<b>Gross Labour Cost (\$)</b>			<b>4,020.00</b>	<b>1,440.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >