



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PC 8305M

| Qty | Description of Parts  | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---|----------------------|---------------------------|-------------------|
|     | <b><u>REPLACEMENT OF PARTS</u></b>  |                      |                           |                   |
| 1   | REAR L/H FENDER PANEL   | DENTED               | 2,232.60                  | 1,860.00          |
| 1   | REAR L/H FENDER GLASS   | CUT                  | 884.60                    | 884.60            |
| 1   | REAR L/H TAILLAMP ASSY  | CRACKED              | 412.20                    | 365.00            |
| 1   | REAR L/H TAILLAMP LOWER COVER   | TO REPAIR SEE LABOUR | 121.60                    | -                 |
| 1   | REAR BUMPER ASSY  | CUT                  | 585.60                    | 585.60            |
| 6   | REAR BUMPER CLIP  | NECESSARY            | 30.00                     | 30.00             |
| 1   | REAR L/H BUMPER SIDE RETAINER   | NOT NECESSARY        | 64.80                     | -                 |
| 1   | REAR END PANEL (OUTER)  | NOT NECESSARY        | 995.50                    | -                 |
|     | LESS 25% DISCOUNT   |                      | -1,331.73                 | -931.30           |
|     |   |                      | 3,995.17                  | 2,793.90          |
|     | <b><u>SPECIAL NETT ITEMS</u></b>  |                      |                           |                   |
| 1   | REAR L/H FENDER DAM RUBBER (SN)   | NOT NECESSARY        | 60.00                     | -                 |
|     |   |                      | 60.00                     | -                 |
|     | <b><u>LABOUR</u></b>  |                      |                           |                   |
|     | TO DISM / REWIRE DAMAGED PORTION.   |                      | 150.00                    | 30.00             |
|     | TO DISM / REFIX INNER SEAT, ROOF LINING.  |                      | 250.00                    | 80.00             |
|     | TO SEND VEHICLE FOR WHEEL ALIGNMENT.  | NOT NECESSARY        | 120.00                    | -                 |
|     | TO PANEL BEAT DAMAGED PORTION AND RENEW FENDER. INCLUSIVE OF THE REPAIR OF REAR L/H TAILLAMP LOWER COVER. |                      | 1,800.00                  | 600.00            |
|     | TO PUTTY AND RESPRAY DAMAGED PORTION.   |                      | 1,000.00                  | 300.00            |
|     | TO SPRAY UNDERCOATING IN REPAIR.  |                      | 250.00                    | 40.00             |
|     | TO DISM / REFIT REAR L/H GLASS.   |                      | 250.00                    | 80.00             |
|     |   |                      | 3,820.00                  | 1,130.00          |
|     | <b>GRAND TOTAL</b>  |                      | <b>7,875.17</b>           | <b>3,923.90</b>   |



|   |  |  |                 |
|---|--|--|-----------------|
| RECOMMENDED COST OF LUMP SUM REPAIRS<br>(TO ITS PRE-ACCIDENT CONDITION) |  |  | <b>3,100.00</b> |
|---|--|--|-----------------|

Report Ref No. CS/FCI22004361/Any3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.