



# 友尼摩哆公司 UNIMOTOR COMPANY

一號加基武吉六道一樓門牌九十四號 新加坡郵區四一七八八三

AUTOBAY @ KAKI BUKIT

No. 1 KAKI BUKIT AVE 6 #01-94 SINGAPORE 417883

TELEPHONE: 6748 2795 FAX: 6747 2373

LKK

Registration No.: 203165/00D

G.D.H.223

TP 1st Cap.  
Xiao Chun.

DATE: 11/10/2022 OUR REF: UAPL1553

REPAIR ESTIMATE YOUR TOYOTA HIACE HIROOF NO: PC8305M

- 1 REAR L/H FENDER PANEL *Denked*
- 1 REAR L/H FENDER GLASS *lt*
- 1 REAR L/H TAILLAMP ASSY *Chud*
- 1 REAR L/H TAILLAMP LOWER COVER *Ris*
- 1 REAR BUMPER ASSY *lt*
- 6 REAR BUMPER CLIP *nn*
- 1 REAR L/H BUMPER SIDE RETAINER *3pe*
- 1 REAR END PANEL (OUTER) *nn*

LESS 25%.....

\$	2,232.60	1860
\$	884.60	
\$	412.20	365
\$	121.60	
\$	585.60	
\$	30.00	
\$	64.80	
\$	995.50	
\$	5,326.90	
\$	1,331.73	
\$	3,995.18	

## SPECIAL NETT:

1 REAR L/H FENDER DAM RUBBER

\$ 60.00 nn

## LABOUR CHARGES:-

TO DISM/REWIRE DAMAGED PORTION

\$ 150.00 30

TO DISM/REFIX INNER SEAT, ROOF LINING.

\$ 250.00 80

TO SEND VEHICLE FOR WHEEL ALIGHTMENT

\$ 120.00 X

TO PANEL BEAT DAMAGED PORTION AND RENEW FENDER.

\$ 1,800.00 600

TO PUTTY AND RESPRAY DAMAGED PORTION

\$ 1,000.00 300

TO SPRAY UNDERCOATING IN REPAIR

\$ 250.00 40

TO DISM/REFIT REAR L/H GLASS

\$ 250.00 80

\$ 7,875.18

total: 3923.90

h/s: 3. PK.

05 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

3.11C