



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBA 27U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	MTG CRACKED	487.60	458.80
1	REAR O/S BUMPER SIDE RETAINER	CRACKED	75.60	75.60
1	REAR O/S TAIL-LAMP	SERVICEABLE	465.80	-
1	REAR O/S TAIL-LAMP APRON PANEL	SERVICEABLE	155.70	-
1	REAR O/S FENDER	BENT	1,567.30	1,469.50
	LESS 25% DISCOUNT		-688.00	-500.98
			2,064.00	1,502.92
	<u>SPECIAL NETT ITEMS</u>			
1	REAR TAIL-GATE ADVERTISEMENT STICKER (SN)	NECESSARY	700.00	550.00
1	REAR REVERSE SENSOR (SN)	SERVICEABLE	200.00	-
			900.00	550.00
	<u>LABOUR</u>			
	REMOVE/RENEW THE ABOVE ACCIDENT PARTS INCLUDING KNOCKING, WELDING & CUTTING		1,400.00	650.00
	TO PUTTY AND SPRAY PAINT.		1,000.00	480.00
	CHECK & RECONNECT WIRING.		30.00	10.00
	REMOVE/REFIT ROOF LINING TO FACILITATE REPAIR ON REAR O/S FENDER.		150.00	80.00
			2,580.00	1,220.00
GRAND TOTAL			5,544.00	3,272.92
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,600.00

Report Ref No. CS/SMO22004362/Kqy3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.