

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKL 3801S

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DENTED / DEFORMED	1,458.60	1,458.60
1	REAR BUMPER BLACK GARNISH	GRAZED	269.85	269.85
1	REAR BUMPER CENTRE PROTECTOR	NO SUCH PARTS	224.60	-
2	REAR BUMPER SIDE CHROME	NECESSARY	336.60	336.60
1	REAR BUMPER TOP CHROME	CRACKED	385.50	305.00
1	REAR BUMPER REINFORCEMENT	BENT	467.50	467.50
2	REAR BUMPER SIDE RETAINER	NOT NECESSARY	35.98	-
1	REAR BUMPER CENTRE RETAINER	NO SUCH PARTS	167.05	-
1	SET REAR BUMPER CLIP	NECESSARY	50.00	50.00
2	TAILLAMP LOWER RETAINER	NOT NECESSARY	308.40	-
1	TAILLAMP (LH)	NOT NECESSARY	642.50	-
1	END PANEL	TO REPAIR SEE LABOUR	1,215.50	-
1	END PANEL TOP GARNISH	NOT NECESSARY	104.33	-
1	REAR BOOT LOCK	NOT NECESSARY	424.05	-
1	REAR BOOT RUBBER	NOT NECESSARY	231.20	-
	LESS 10% DISCOUNT		-632.17	-288.76
			5,689.49	2,598.79
	SPECIAL NETT ITEMS			
2	REVERSE SENSOR (SN)	SHORTED	359.55	359.55
1	END PANEL SEALANT (SN)	NOT NECESSARY	60.00	-
			419.55	359.55
	<u>LABOUR</u>			
	TO REMOVE & REINSTALL REVERSE SENSORS.		120.00	50.00
	TO CHECK REAR ELECTRICAL WIRING SYSTEM.		120.00	20.00
	LABOUR TO REMOVE,CUT,CHANGE & PANEL BEATING.INCLUSIVE OF THE REPAIR OF END PANEL.		750.00	500.00
	TO PUTTY AND RESPRAY AFFECTED AREAS.		650.00	500.00
			1,640.00	1,070.00
	GRAND TOTAL		7,749.04	4,028.34

Report Ref No. CS/AGI22004363/Uvy3n2





RECOMMENDED COST OF LUMP SUM REPAIRS	3,200.00
(TO ITS PRE-ACCIDENT CONDITION)	·

Report Ref No. CS/AGI22004363/Uvy3n2

CHUA KANG SENG Licensed Appraiser