

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/HLA22004366/KQY3N2**Date:** 15/06/2022**REFERENCE**

Handling Insurer:	HL Assurance Pte Ltd	Policy No:	MP314156
<b>Claimant Vehicle No :</b>	SHC5497G	<b>Insured Vehicle No :</b>	SLS5918C
Date of Loss:	07/05/2022	Nature of Claim:	TP
		Claim No:	MPC03394

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SHC5497G</b>		
Make & Model:	TOYOTA PRIUS, 1.5 (A)	Engine No:	2ZR2G98249
Reg. Date:	31/03/2021 (Man. Year: 2020)	Chassis No:	JTDKB3FU403092114
Colour:	Metallic Pearl White/Red	Odometer:	40349 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Lanvigaton 8 mm	Rear Left Side:	Dunlop 3 mm
Front Right Side:	Lanvigaton 8 mm	Rear Right Side:	Dunlop 3 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,695.70	280.87	2,414.83	89.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,100.00	300.00	4,800.00	94.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>7,795.70</b>	<b>580.87</b>	<b>7,214.83</b>	<b>92.55</b>
<b>+ GST 7.00/7.00% (S\$)</b>	545.70	40.66	505.04	92.55
<b>Nett Amount (S\$)</b>	<b>8,341.40</b>	<b>621.53</b>	<b>7,719.87</b>	<b>92.55</b>

**INSPECTION**

Date of Assignment:	11/05/2022		
Date Inspected:	10/05/2022	Inspected At:	Trans-Cab Services Pte Ltd (HQ) 2 Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	1.5 days		

**Adjuster:** KENNETH KONG**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

Different 1 cents -Finalise confirm amount: \$580.88

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 15 Jun 2022)
<b>Parts:</b>	144	TOYOTA PRIUS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHC5497G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER,REAR BUMPER	Repair	485.60 FL	*- FL
2	1		*REINFORCEMENT SUB-ASSY,REAR BUMPER	Repair	332.70 FL	*- FL
3	1		*GUARD,REAR BUMPER,CENTER	Dented	374.50 FL	*374.50 FL
4	1		*SEAL,REAR BUMPER SIDE,RH	Serviceable	118.30 FL	*- FL
5	1		*RETAINER,REAR BUMPER SIDE,RH	Serviceable	132.60 FL	*- FL
6	1		*SEAL,REAR BUMPER SIDE,LH	Serviceable	118.30 FL	*- FL
7	1		*RETAINER,REAR BUMPER SIDE,LH	Serviceable	132.60 FL	*- FL
8	1		*COVER,REAR BUMPER,LOWER	Serviceable	22.00 FL	*- FL
9	1		*PANEL SUB-ASSY,BODY LOWER BACK	Repair	651.00 FL	*- FL
10	1		*REAR BUMPER SIDE CLIP	Not Necessary	60.00 FS	*- FS
11	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
12	1		*SET REAR BUMPER CLIP	Not Necessary	85.00 FS	*- FS
13	1		*REAR BUMPER RETAINER CLIP	Not Necessary	75.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>3,287.60</b>	<b>374.50</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	591.90	93.63
<b>Total Parts (\$\$)</b>	<b>2,695.70</b>	<b>280.87</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	0.00
2	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	0.00
3	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	1,600.00	80.00
4	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT TO FACILITATE BODYWORK REPAIR	New	380.00	0.00
5	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,600.00	220.00
6	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	0.00
7	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	170.00	0.00
8	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	0.00
9	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
10	TO REMOVE AND REFIT OF REAR FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>5,100.00</b>	<b>300.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >