



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBR 2971R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT FORK ASSY	SERVICEABLE	980.00	-
1	FORK UNDER BRACKET COVER	NOT NECESSARY	190.00	-
1	FRONT SPORT RIM	NOT NECESSARY	550.00	-
1	FRONT BRAKE DISC	NOT NECESSARY	180.00	-
1	FRONT RIM SHAFT	NOT NECESSARY	52.00	-
1	SIDE MIRROR	CUT	180.00	150.00
1	HANDLE-BAR	BENT	135.00	135.00
1	HANDLE-BAR BALANCER SET	CUT	125.00	80.00
1	HAND GRIP O/S	TORN	60.00	60.00
1	BRAKE LEVERS O/S	CUT	150.00	60.00
1	FRONT COWLING INNER PANEL (1 SET)	CUT	300.00	300.00
1	FRONT INNER PANEL	CUT	160.00	160.00
1	FRONT COVER	SERVICEABLE	175.00	-
1	FRONT CENTRE COVER	SERVICEABLE	185.00	-
1	FRONT SIDE COVER	CUT	205.00	180.00
2	FOOTSTEP PANELS	O/S CUT	310.00	155.00
1	REAR HANDLE	TO REPAIR SEE LABOUR	298.00	-
1	REAR SIDE COVER	CUT	215.00	215.00
1	EXHAUST ASSY	TO REPAIR SEE LABOUR	2,980.00	-
1	EXHAUST PROTECTOR	DISTORTED	125.00	125.00
1	LEG SHIELD COVER (FRONT INNER COVER) (ADDITIONAL)	CRACKED	340.00	280.00
	LESS 10% DISCOUNT		-789.50	-190.00
			7,105.50	1,710.00
	<b><u>SPECIAL NETT ITEMS</u></b>			
2	FORK OILS (SN)	NOT NECESSARY	30.00	-
2	FORK OIL SEALS (SN)	NOT NECESSARY	56.00	-
1	STEERING CONE (1 SET) (SN)	NOT NECESSARY	120.00	-
1	NUMBER PLATE (1 SET) (SN)	NOT NECESSARY	38.00	-

Report Ref No. CS/AGI22004367/Uqy3m4



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	X MAX EMBLEM (SN)	NECESSARY	80.00	60.00
			324.00	60.00
	<b>LABOUR</b>			
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING.	NOT NECESSARY	80.00	-
	TO PROVIDE LABOUR. INCLUSIVE OF THE REPAIR OF REAR HANDLE AND EXHAUST ASSY.		480.00	300.00
	TO RE-SPRAY PAINT.		480.00	250.00
			1,040.00	550.00
<b>GRAND TOTAL</b>			<b>8,469.50</b>	<b>2,320.00</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,850.00</b>

Report Ref No. CS/AGI22004367/Uqy3m4

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.