



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBJ 4293T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT FUSE BOX	CRACKED	280.00	280.00
1	FRONT FUSE BOX BRACKET	NOT NECESSARY	95.00	-
1	FRONT WHEEL REAR MUDGUARD LH	DEFORMED	186.70	186.70
1	FRONT WHEEL REAR MUDGUARD LOWER BRACKET LH	NOT NECESSARY	85.00	-
1	FRONT WHEEL REAR MUDGUARD UPPER BRACKET LH	NOT NECESSARY	80.00	-
1	REAR SIDE GATE LH	DENTED	1,778.90	1,778.90
3	REAR SIDE GATE HINGE LH @\$95.90	DENTED (2 PCS ONLY)	287.70	191.80
1	REAR SIDE GATE STOPPER LH	NOT NECESSARY	24.60	-
1	REAR CARGO BED SIDE FRAME LH	TO REPAIR SEE LABOUR	1,576.20	-
1	REAR WHEEL FRONT FENDER LH	DISTORTED	243.80	243.80
1	REAR WHEEL BACK FENDER LH	TO REPAIR SEE LABOUR	239.90	-
1	REAR AXLE	NOT NECESSARY	2,887.15	-
1	GEAR BOX GASKET	NOT NECESSARY	219.40	-
1	REAR WHEEL HUP SHAFT RH	NOT NECESSARY	874.40	-
1	REAR WHEEL HUP RH	NOT NECESSARY	396.10	-
1	REAR WHEEL HUP BEARING RH	NOT NECESSARY	241.30	-
1	REAR WHEEL HUP OIL SEAL RH	NOT NECESSARY	74.60	-
	LESS 25% DISCOUNT		-2,392.69	-670.30
			7,178.06	2,010.90
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRONT WHEEL TYRE RH (SN)	NOT NECESSARY	350.00	-
1	REAR WHEEL TYRE RH (SN)	NOT NECESSARY	280.00	-
1	BRAKE OIL (SN)	NOT NECESSARY	40.00	-
1	GEAR OIL (SN)	NOT NECESSARY	180.00	-
1	BATTERY (SN)	NOT NECESSARY	250.00	-
			1,100.00	-

Report Ref No. CS/AIS22004368/Any3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	TO PANEL BEAT ,WELD ,CUT ,ADJUST KNOCK.INCLUSIVE OF THE REPAIR OF REAR CARGO BED SIDE FRAME LH AND REAR WHEEL BACK FENDER LH .		1,200.00	400.00
	TO PUTTY ,SPRAY PAINT ,POLISH WAX.		1,000.00	600.00
	TO SPRAY TUFF COAT.		250.00	60.00
	WIRING BULB CHECKING.		80.00	30.00
	TRANSFER SIDE GATE MECHANISM .	NOT NECESSARY	80.00	-
	REMOVE AND REFIX RAILLING.	NOT NECESSARY	150.00	-
	REMOVE AND REFIX REAR UNDERCARRIAGE.	NOT NECESSARY	650.00	-
	FOUR WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
	REMOVE AND REFIX REAR CANOPY.	NOT NECESSARY	250.00	-
	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC.	NOT NECESSARY	180.00	-
			3,960.00	1,090.00
	<b>GRAND TOTAL</b>		<b>12,238.06</b>	<b>3,100.90</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>2,400.00</b>

Report Ref No. CS/AIS22004368/Any3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.