



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMQ 6236D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
1	REFLECTOR, TAIL LAMP, LH (SN)	NOT NECESSARY	100.00	-
1	FACE, RR BUMPER (SN)	CUT	1,119.00	1,119.00
1	BRKT, R/BMPR FACE SIDE, LH (SN)	NOT NECESSARY	27.00	-
1	EXTENSION, RR BUMPER (SN)	CUT	358.00	358.00
1	SET BODY KIT, OUTLANDER (SN)	CUT	1,554.00	1,554.00
			3,208.00	3,051.00
<u>LABOUR</u>				
	REPLACE REAR BUMPER PANEL & AFFECTED AREA.		1,280.00	640.00
	PAINT WORK ON REAR BUMPER & REAR LH FENDER.		1,650.00	550.00
	REMOVE & REPLACE BODY KIT.		150.00	120.00
	REMOVE & INSTALL REAR PARKING ASSIST FOR FACILITATE REPAIR.		150.00	80.00
	PERFORM RUST PREVENTION.	NOT NECESSARY	80.00	-
	TO APPLY SEALANT ON AFFECTED AREA.	NOT NECESSARY	50.00	-
	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM.		150.00	100.00
	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM.		280.00	280.00
			3,790.00	1,770.00
GRAND TOTAL			6,998.00	4,821.00

RECOMMENDED COST OF REPAIRS			4,821.00
------------------------------------	--	--	-----------------

Report Ref No. CS/UOI22004369/Eqy3e2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.