

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22004370/UVY3N2**Date:** 07/06/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNA00007232100

Claimant Vehicle No : SLN3988P **Insured Vehicle No :** SJY4307P

Date of Loss: 29/04/2022 Nature of Claim: TP Claim No: SNM22D203081/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLN3988P**

Make & Model: AUDI Q5, 2.0 (A) Engine No: CNC181806

Reg. Date: 29/04/2017 (Man. Year: 2016) Chassis No: WAUZZZ8R7HA077777

Colour: Beige Odometer: 83296 km

Engine Capacity: 1984 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/60R18 Rear Tyre Size: 235/60R18

Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm

Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,742.55	10,262.39	6,480.16	38.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,580.00	1,350.00	1,230.00	47.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,322.55	11,612.39	7,710.16	39.90
Approved Total (Overridden) (S\$)		9,200.00		
(S\$)	19,322.55	9,200.00	10,122.55	52.39
+ GST 7.00/7.00% (S\$)	1,352.58	644.00	708.58	52.39
Nett Amount (S\$)	20,675.13	9,844.00	10,831.13	52.39

INSPECTION

Date of Assignment: 11/05/2022

Date Inspected: 10/05/2022 Inspected At: LEE BROTHERS AUTOMOTIVE PTE. LTD. (HQ)
1 Kaki Bukit Ave 6, #02-47 Autobay @ Kaki Bukit
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Jun 2022)
Parts:	143	AUDI Q5 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLN3988P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deep Cut	1,835.90 FL	*1,835.90 FL
2	1		*REAR BUMPER LOWER	Repair	1,135.60 FL	*- FL
3	1		*REAR BUMPER LAMP-LH	Not Necessary	281.35 FL	*- FL
4	1		*REAR BUMPER SIDE BRACKET	Not Necessary	110.25 FL	*- FL
5	1		*REAR DOOR-LH	Dented/Warped	2,877.35 FL	*2,877.35 FL
6	1		*REAR DOOR PROTECTOR	Repair	341.55 FL	*- FL
7	1		*REAR DOOR PROTECTOR MOULDING	Scratched	280.63 FL	*280.63 FL
8	1		*REAR DOOR GLASS OUTER MOULDING	Not Necessary	261.42 FL	*- FL
9	1		*REAR DOOR GLASS RUN CHANNEL	Not Necessary	288.90 FL	*- FL
10	1		*REAR DOOR INSULATION	Not Necessary	131.20 FL	*- FL
11	1		*REAR DOOR W/STRIP	Necessary	181.95 FL	*181.95 FL
12	1		*REAR DOOR TRIM BOARD	Not Necessary	815.90 FL	*- FL
13	1		*REAR SPORT WHEEL-LH	Warped/Cut	1,864.65 FL	*1,321.00 FL
14	1		*REAR SHOCK ABSORBER-LH	Bent/Twisted	1,557.35 FL	*1,557.35 FL
15	1		*REAR SUSPENSION TOP GUIDE	Not Necessary	593.25 FL	*- FL
16	1		*REAR SUSPENSION LOWER ARM	Twisted	909.20 FL	*909.20 FL
17	1		*REAR KNUCKLE ARM	Bent	1,157.25 FL	*1,157.25 FL
18	1		*REAR WHEEL HUB BEARING	Damaged	629.25 FL	*629.25 FL
19	1		*REAR DRIVE SHAFT-LH	Not Necessary	1,833.95 FL	*- FL
20	1		*REAR TYRE-LH	Serviceable	450.00 FS	*- FS
21	1		*SET BUMPER CLIP	Necessary	60.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	17,596.90	10,799.88
- List Item Discount on L Items 5.00/5.00% (\$)	854.35	537.49
Total Parts (\$)	16,742.55	10,262.39

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK REAR ELECTRICAL WIRING	New	50.00	20.00
2	TO REMOVE & REPLACE REAR UNDERCARRIAGE PARTS	New	350.00	150.00
3	TO CONDUCT COMPUTERISED WHEEL ALIGNMENT	New	120.00	80.00
4	TO TUFF KOTE	New	80.00	0.00
5	TO PUTTY,SPRAY PAINT & POLISH AFFECTED PARTS	New	1,080.00	600.00
6	TO PANEL BEAT,CUT,WELD,REMOVE & REPLACE DAMAGED PARTS	New	900.00	500.00
Gross Labour Cost (\$)			2,580.00	1,350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >