



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 9215J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	TO REPAIR SEE LABOUR	1,885.00	-
1	FRONT BUMPER INNER SPONGE	NOT NECESSARY	180.00	-
2	FRONT BUMPER PARKING SENSOR @\$195.00	DAMAGED (1PC ONLY)	390.00	195.00
2	FRONT BUMPER PARKING SENSOR 'O' RING @\$12.00	NECESSARY	24.00	24.00
20	FRONT BUMPER RIVET @\$9.00	NOT NECESSARY	180.00	-
1	FRONT BUMPER SIDE BRACKET	NOT NECESSARY	115.00	-
2	FRONT BUMPER SIDE RETAINER L/R @\$25.00	NOT NECESSARY	50.00	-
1	FRONT LH FENDER	TO REPAIR SEE LABOUR	1,015.00	-
1	FRONT LH FENDER INNER SHIELD (FRONT)	NOT NECESSARY	145.00	-
1	FRONT LH HEADLAMP	CRACKED	3,679.00	3,290.00
	LESS 10% DISCOUNT		-766.30	-350.90
			6,896.70	3,158.10
1	FRONT LH WHEEL RIM (SN)	CUT	1,550.00	1,100.00
	LESS 10% DISCOUNT		-155.00	-
			1,395.00	1,100.00
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT BUMPER CLIPS (SN)	NOT NECESSARY	50.00	-
1	SET FRONT LH FENDER INNER SHIELD CLIPS (SN)	NOT NECESSARY	50.00	-
			100.00	-
<u>LABOUR</u>				
	TO RESET SYSTEM AFTER REPAIR WORKS.	NOT NECESSARY	250.00	-
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING, AND REWIRE FOR PARKING SENSOR.		60.00	60.00
	TO ROAD TEST DRIVING, CHECK AND RESETTNG WHEEL ALIGNMENTS SYSTEM.		100.00	80.00
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.		700.00	500.00

Report Ref No. CS/SMR22004372/Aqy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF FRONT BUMPER AND FRONT LH FENDER.		600.00	350.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		50.00	30.00
			1,760.00	1,020.00
GRAND TOTAL			10,151.70	5,278.10
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,200.00

Report Ref No. CS/SMR22004372/Aqy3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.