

Block 805D, Keat Hong Close. #13-88 Singapore 684805

YONG WOON HOU c/o JSSM AUTOSOLUTIONS PTE LTD **8 KAKI BUKIT AVENUE 4** #02-13 PREMIER @ KAKI BUKIT **SINGAPORE 415875** 

Report No : ALLIN-2204-17

Date

: 24.03.2023

Reference

Requested by

Workshop, owner's behalf

Date of Request Date of Accident -

26/4/2022 23/4/2022 9/5/2022

Date of Inspection Inspected at

JSSM AUTOSOLUTIONS PTE LTD

8 Kaki Bukit Avenue 4

#02-13 Premier @ Kaki Bukit

Singapore 415875

**Vehicle Details** 

Vehicle No. Year Make

SLA4056R

2015

1197 cc

: Engine No. HRA2239065A :

**Engine Capacity** . Air-Con

: YES Seat Belt : YES

1

:

Make & Model

I NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR

Colour Chassis No. : WHITE I SJNFEAJ11U1587713

Mileage

: NA

Radio/CD/Cassette Rims

: YES

: SPORTS

**General Condition of Vehicle** 

**General Condition** Brakes

GOOD

**SERVICEABLE** 

Steering

**SERVICEABLE** 

Modification

: NIL

Handbrake

\* SERVICEABLE

Rim **Tread Balance** Tyres Make Size Front Right YOKOHAMA 215/60 R17 **SPORT** 80% Front Left YOKOHAMA 215/60 R17 **SPORT** 80% Rear Right 215/60 R17 **SPORT** 80% YOKOHAMA 80% Rear Left YOKOHAMA 215/60 R17 **SPORT** 

**Assessment** 

Spare Parts Labour Charges Paint Work **Towing Charges** Total

Repairer's Estimate \$ 7,427.00 \$ 2,230.00 \$ 1000.00 \$ 10,657.00

Recommendation \$ 6,684.30 \$ 2,230.00 \$ 1000.00 9,914.30

Recommend Lum Sum Repairs

Reduction

7,931.44 2,725.56

Estimated Period Required for Repair

: 05 Days



Block 805D, Keat Hong Close. #13-88 Singapore 684805

### **ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS**

Vehicle No:

SLA4056R

Report No

ALLIN-2204-17

Chassis No: Engine No: SJNFEAJ11U1587713

HRA2239065A

Date

: 24.03.2023

Replacement of Damaged Parts						
5/No.	QTY	Description	Condition / Remarks	Repairer's Estimates	My Recommendation	
1	1	Left Front Door	Damaged	\$ 1,422.00	\$ 1,279.80	
2	1	Left Rear Door	Damaged	\$ 1,422.00	\$ 1,279.80	
3	1	Left Front Door Lower Garnish	Scratches	\$ 365.00	\$ 328.50	
4	1	Left Rear Door Lower Garnish	Scratches	\$ 365.00	\$ 328.50	
5	1	Left Front Door PW Motor	Faulty	\$ 496.00	\$ 446.40	
6	1	Left Front Door PW Rack	Distorted	\$ 377.00	\$ 339.30	
7	1	Left Front Door PW Motor Switch	Faulty	\$ 339.00	\$ 305.10	
8	1	Left Front Door Lock	Faulty	\$ 196.00	\$ 176.40	
9	1	Left Front Door Hinge	Distorted	\$ 115.00	\$ 103.50	
10	1	Left Front Fender	Scratches	\$ 798.00	\$ 718.20	
11	1	Centre Left C pillar	Impacted	\$ 1,122.00	\$ 1,009.80	
12	1	Left Front Door weather Strip	Necessary	\$ 166.00	\$ 149.40	
13	1	Left Front Door Handle	Impacted	\$ 244.00	\$ 219.60	
				\$ 7,427.00	\$ 6,684.30	

Total (Parts): \$ 7,427.00 -10% \$ 6,684.30

**Labour Charges** 

14	To fix & dismantle and remove damaged Left Portions;	\$ 800.00
	affected damaged portion.	
15	To check wiring	\$ 180.00
16	Welding and cutting of affected panels, including chassis alignment.	\$ 1,250.00
17	Spray painting for Left Front to Rear Portions affected parts	\$ 1,000,00

Total Labour: \$ 3,230.00

Total cost of repairs (Total cost of parts + Total Labour Cost) \$ 9,914.30

Less 20% **\$ 7,931.44** 



Block 805D, Keat Hong Close. #13-88 Singapore 684805

Vehicle No:

**SLA4056R** 

Report No.:

Appraiser Name: Lim Chang Liang ALLIN-2204-17

#### Point of Impact

LH Front and Rear Portion of the car Impacted.

#### Recommendation

The vehicle was inspected throughly based on the repairer's estimate against the actual damages found on the vehicle. My findings and recommendation are listed as per attached.

My adjusted amount for the cost of repair is \$7,931.44.

#### Conclusion

The repairer has agreed to undertake repairs at a lump sum of \$7,900.00 corresponding to labour charges, spray painting and replacement of parts.

SURVEYED WITHOUT PREJUDICE

**ALLIN AUTOMOTIVE APPRAISERS** 

Page 3 of 3





















































































