

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
	NTUC INCOME IN	SURANCE CO-OPERATIVE LTD	Ref:	CS3/INC22004387/Gty3e2
	73 BRAS BASAH F #05-01 NTUC TRA 189556	ROAD DE UNION HOUSESINGAPORE	Date:	27/05/2022
	ATTN: CHRYLLIS	QUAH	Code:	INC
1.	Policy Particulars :- (THIRD PARTY CLAIM)			
	Insured Veh.	SMT 9215D	Veh. Inspected	SLD 2821X
	Policy No.		Coverage (\$)	0.00
	Claim No.	MT/1171706-002	Excess (\$)	0.00
	Assign From	JESS TOH	Assign Date	10/05/2022
2.	. Vehicle Particulars & Condition			
	Make & Model	TOYOTA VIOS E	c.c	1497
	Engine No.	HIDDEN	Year of Reg.	2010
	Chassis No.	MR053HY9305168732	Colour	GREEN
	Odometer	269954 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/55 R15	FIRENZA	6 mm
	L/H Front Tyre	195/55 R15	FIRENZA	6 mm
	R/H Rear Tyre	195/55 R15	FIRENZA	6 mm
	L/H Rear Tyre	195/55 R15	FIRENZA	6 mm
4. Description of Damages				
		STAINED DAMAGES AT THE N/S E AFFECTED DUE TO COLLISION		
5.	General Information			
	Accident Date	08/05/2022	Inspect Date / Time	18/05/2022 (03:30 PM)
	Survey held at	GARAGE 13 PTE LTD	-	
		8 KAKI BUKIT AVE 4 #03-46 PREMIER SINGAPORE 415875		
5a.	Remarks			
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

Report Ref No. CS3/INC22004387/Gty3e2

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.