

# PRO-OPTION SERVICES

Mailing address: Blk 189B Rivervale Drive, #04-1004, Singapore 542189

Email: [mirage1195@gmail.com](mailto:mirage1195@gmail.com); Mobile: 9061 0543

## ACCIDENT VEHICLE INSPECTION REPORT

Report no : 373M1121.KHM  
Vehicle no : FBM4641G

### **1 REFERENCE**

Date of inspection : 16 November 2021  
Requested by : Lai Chen Mun, Jonathan  
Blk 312 Ang Mo Kio Ave 3  
#11-2104  
Singapore 560312  
Type of survey : Independent  
Repairer : Keng Hock Motor  
188 Yio Chu Kang Road Singapore 545635  
Date of accident : 8 November 2022

### **2 VEHICLE DATA**

Make/model : Yamaha Xmax 300  
Year of registration : 2017  
Engine capacity : 300 cc  
Colour : White

### **3 STATIC CONDITION CHECK**

Steering : Serviceable  
Foot brakes : Serviceable  
Hand brakes : Serviceable  
Paintwork : Good  
General Condition : Good

### **4 TIRE CONDITION CHECK**

	<u>mm/MAKE</u>	<u>SIZE</u>
Front tread	: 5 mm/Pirelli	120/70-15
Rear tread	: 5 mm/Pirelli	150/70-14

### **5 BRIEF DESCRIPTION OF DAMAGE**

Exhaust muffler bent, exhaust muffler protector dented/scraped, RH beely panel scraped, etc. Please see para. 8 of this report for more details.

### **6 REMARKS**

This inspection is carried out on a "WITHOUT PREJUDICE" basis and I have not authorized any repairs.

### **7 RECOMMENDATION**

Cost of repairs : \$1,240.00  
Estimated no of days : Two (2)

**8 ASSESSMENT OF DAMAGE AND COSTS**

Report no: 373M1121.KHM  
Vehicle no: FBM4641G

**A SPARE PARTS**

<u>Description</u>	<u>Qty</u>	<u>Assessed Condition</u>	<u>Repairer's Amount</u>	<u>Revised Amount</u>
Exhaust muffler	1	bent	980.00	980.00
Exhaust muffler protector	1	scraped/dented	120.00	120.00
RH belly panel	1	to repair	185.00	0.00
Subtotal of the above			1,285.00	1,100.00
Discount 10%			128.50	110.00
Total cost of parts:			<u>1,156.50</u>	<u>990.00</u>

**B LABOUR**

Labour for dismantle and remove all damaged parts, renew and install new parts. 200.00 100.00

Spray painting. 200.00 150.00

Total cost of labour: 400.00 250.00

Total cost of repair: 1,556.50 1,240.00

**7 CONCLUSION**

The revised or adjusted cost of repairs to restore the vehicle is \$1,240.00

(a) The recommended cost of repair would be \$1,240.00

(b) The estimated number of days for the repairs would be Two (2)  
(Post Repair Inspection conducted on 2 December 2021)

*The above recommendations in my view are fair and reasonable for the restoration of the vehicle to its pre-accident condition.*

**Note: Lump Sum Repair Basis**

*This means the repairer is allowed to replace the damaged parts with used, reconditioned or new parts, or repair it to a roadworthy condition.*

Yours faithfully



.....  
Liaw Leong San  
Licensed Automotive Appraiser

Dated: 21 March 2022

Report no: 373M1121.KHM

Vehicle no: FBM4641G



Report no: 373M1121.KHM

Vehicle no: FBM4641G



Report no: 373M1121.KHM

Vehicle no: FBM4641G



Report no: 373M1121.KHM

Vehicle no: FBM4641G



POST REPAIR

Report no: 373M1121.KHM

Vehicle no: FBM4641G



POST REPAIR

Report no: 373M1121.KHM

Vehicle no: FBM4641G



POST REPAIR

Report no: 373M1121.KHM

Vehicle no: FBM4641G

