



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 ATTN: LEE MING YAO GEORGE		Ref: CS3/AIG20013257/Gty3e2-1 Date: 25/05/2022 Code: AIG	
<b>1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)</b>			
Insured Veh.	GBJ 1843B	Veh. Inspected	SGB 2B
Policy No.	2070013783	Coverage (\$)	0.00
Claim No.	9552386213SG	Excess (\$)	0.00
Assign From	LEE MING YAO GEORGE	Assign Date	10/05/2022
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	BENTLEY CONTI FS	c.c	5998
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	SCBBE53W67C048279	Colour	BLACK
Odometer	35794 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	275/40Z R19	MICHELIN	6 mm
L/H Front Tyre	275/40Z R19	MICHELIN	6 mm
R/H Rear Tyre	275/40Z R19	MICHELIN	6 mm
L/H Rear Tyre	275/40Z R19	MICHELIN	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	20/11/2020	Inspection Date	11/05/2022
Survey held at	51 UBI AVE 1 #01-11 PAYA UBI INDUSTRIAL PARK		
Repairer	LUCK7WIN		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		25 Working Days	