

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM22004390/Tqy3m4	
	8 SHENTON WAY SINGAPORE 0688		Date:	06/06/2022		
	ATTN: HO WINNIE			Code:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SFS 2689D	Veh. Inspected	ı	FBE 9735D	
	Policy No.	P2264749	Coverage (\$)		0.00	
	Claim No.	S2M040JS	Excess (\$)		0.00	
	Assign From	HO WINNIE	Assign Date		11/05/2022	
2.	Vehicle Particulars & Condition					
	Make & Model	YAMAHA RXZ	c.c		133	
	Engine No.	HIDDEN	Year of Reg.		2010	
	Chassis No.	PMY5PV100A0033720	Colour		RED	
	Odometer	-	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	2.50-18	DUNLOP		5 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	2.50-18	DUNLOP		5 mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
	THE VEHICLE SUS BODY.	E VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND O/S DY.				
5.	General Information					
	Accident Date	08/05/2022	Inspect Date /	Time	11/05/2022 (01:00 PM)	
	Survey held at	EQUATOR BROTHERHOOD				
		25 KAKI BUKIT ROAD 4 #03-19 SYNERGY @KB SINGAPORE 417800				
5a.	Remarks					
	B) THE REPAIR ES THE REPAIRER W C) ENCLOSED PLE	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000				
5b. Estimate Days of Repair						
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days					

Report Ref No. CS3/ASM22004390/Tqy3m4

Inspected By

MOHAMAD TAUFIKH

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

Automotive Assessor REGD Auto Consultant-SAE, Licensed Appraiser