

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22004396/ANCE2

Date: 26/08/2022

REFERENCE

Insured/Claimant: SAMEEN HAMED FAROOQUI Policy No: 2100478218-05
Date of Loss: 30/04/2022 Nature of Claim: OD Claim No: 0542474580SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGK8921Z**
Make & Model: AUDI Q5, 2.0 TFSI Quattro (180BHP) (A) Engine No: CNC172298
Reg. Date: 13/08/2016 (Man. Year: 2016) Chassis No: WAUZZZ8R8HA013859
Colour: Black Odometer: 35506 km
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$105,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R19 Rear Tyre Size: 235/55 R19
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,669.00	5,040.24	10,628.76	67.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,372.00	2,272.00	6,100.00	72.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,041.00	7,312.24	16,728.76	69.58
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	23,041.00	6,312.24	16,728.76	72.60
+ GST 7.00/7.00% (S\$)	1,612.87	441.86	1,171.01	72.60
Nett Amount (S\$)	24,653.87	6,754.10	17,899.77	72.60

INSPECTION

Date of Assignment: 11/05/2022
Date Inspected: 10/05/2022 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,896.00 FS	*2,316.80 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	287.00 FS	*- FS
3	1		*FRONT BUMPER SPOILER	Deformed	695.00 FS	*556.00 FS
4	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	235.00 FS	*- FS
5	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	127.00 FS	*- FS
6	4		*FRONT BUMPER PULL STRAP	Not Necessary	231.00 FS	*- FS
7	2		*FRONT BUMPER SECURING STRIP - LH / RH	Not Necessary	84.00 FS	*- FS
8	1		*FRONT BUMPER TOP COVER	Not Necessary	143.00 FS	*- FS
9	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Missing	393.00 FS	*314.00 FS
10	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	753.00 FS	*- FS
11	1		*FRONT BUMPER REINFORCEMENT BEAM COVER	Not Necessary	73.00 FS	*- FS
12	1		*FRONT BUMPER GUIDE SECTION - LH	Not Necessary	42.00 FS	*- FS
13	2		*FRONT BUMPER SUPPORT - LH / RH	Not Necessary	68.00 FS	*- FS
14	4		*FRONT BUMPER POP RIVET	Necessary	7.00 FS	*5.44 FS
15	1		*CAUTION STICKER	Not Necessary	16.00 FS	*- FS
16	1		*AIR COND STICKER	Not Necessary	9.00 FS	*- FS
17	1		*RADIATOR GRILLE	Cut	2,124.00 FS	*1,699.20 FS
18	1		*RADIATOR GRILLE STRIKER PLATE	Not Necessary	146.00 FS	*- FS
19	1		*QUATTRO EMBLEM	Necessary	111.00 FS	*88.80 FS
20	2		*FRONT PARKING AID SENSOR (NPA)	Not Necessary	0.00 FS	*- FS
21	4		*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	6.00 FS	*- FS
22	1		*HORN - LH	Not Necessary	214.00 FS	*- FS
23	1		*HORN BRACKET - LH	Not Necessary	28.00 FS	*- FS
24	2		*HEADLIGHT MOUNTING - LH / RH	Not Necessary	264.00 FS	*- FS
25	1		*HEADLIGHT RETAINING PLATE	Not Necessary	87.00 FS	*- FS
26	1		*HEADLIGHT - LH	Not Necessary	2,894.00 FS	*- FS
27	1		*LIFT CYLINDER - LH	Not Necessary	223.00 FS	*- FS
28	1		*LIFT CYLINDER HOSE	Not Necessary	204.00 FS	*- FS
29	1		*HALOGEN FOG LAMP	Not Necessary	332.00 FS	*- FS
30	1		*LOCK CARRIER	Not Necessary	1,226.00 FS	*- FS
31	1		*LOCK CARRIER BRACKET - LH	Not Necessary	43.00 FS	*- FS
32	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Not Necessary	21.00 FS	*- FS
33	6		*RADIATOR COOLANT	Not Necessary	282.00 FS	*- FS
34	1		*RADIATOR AIR GUIDE - LH	Not Necessary	28.00 FS	*- FS
35	1		*RADIATOR AIR GUIDE COVER - UPPER	Not Necessary	34.00 FS	*- FS
36	1		*RADIATOR SEALING STRIP - LOWER	Not Necessary	25.00 FS	*- FS
37	1		*NOISE INSULATION - FRONT	Not Necessary	908.00 FS	*- FS
38	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
39	1		*SUNDRIES	Not Necessary	350.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 15,669.00 5,040.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	0.00
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT PRESSURISE, VACUUM AND REGAS	New	1,700.00	0.00
4	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,000.00	500.00
5	TO RESPRAY FRONT BUMPER AND FRONT BUMPER LOWER SPOILER	New	1,600.00	1,100.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			8,372.00	2,272.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >