

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG22004397/AVCE2

**Date:** 29/08/2022

### REFERENCE

|                   |             |                  |            |           |              |
|-------------------|-------------|------------------|------------|-----------|--------------|
| Insured/Claimant: | GOH TOH HAI | Policy No:       | 1900119348 |           |              |
| Date of Loss:     | 07/05/2022  | Nature of Claim: | OD         | Claim No: | 1933455732SG |

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |  |             |                   |
|-----------------------------|--|-------------|-------------------|
| Reg No:                     | SMN791Y                                    |             |                   |
| Make & Model:               | AUDI A5, 2.0 SB TFSI S TRONIC (DESIGN) (A) | Engine No:  | CVK084568         |
| Reg. Date:                  | 24/07/2019 (Man. Year: 2019)               | Chassis No: | WAUZZZF55KA061245 |
| Colour:                     | Blue                                       | Odometer:   | 41761 km          |
| Engine Capacity:            | 1984 cc                                    |             |                   |
| Market Value/New Car Price: | S\$165,000.00                              |             |                   |
| Sum Insured (S\$):          | Market Value/New Car Price                 |             |                   |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

### CONDITION OF TYRES

|                   |                  |                  |                  |
|-------------------|------------------|------------------|------------------|
| Front Tyre Size:  | 255/35 R19       | Rear Tyre Size:  | 255/35 R19       |
| Front Left Side:  | Bridgestone 6 mm | Rear Left Side:  | Bridgestone 6 mm |
| Front Right Side: | Bridgestone 6 mm | Rear Right Side: | Bridgestone 6 mm |

The above values represent the remaining tyre tread depth

| COST OF CLAIMS                      | Repairer's       | Adjuster's       | Difference       | Diff %       |
|-------------------------------------|------------------|------------------|------------------|--------------|
| Parts                               | 37,993.00        | 20,787.76        | 17,205.24        | 45.29        |
| Miscellaneous Items                 | 0.00             | 0.00             | 0.00             |              |
| Labour                              | 10,672.00        | 5,202.00         | 5,470.00         | 51.26        |
| Paintwork Labour                    | 0.00             | 0.00             | 0.00             |              |
| Towing                              | 0.00             | 0.00             | 0.00             |              |
| <b>Calculated Gross Total (S\$)</b> | <b>48,665.00</b> | <b>25,989.76</b> | <b>22,675.24</b> | <b>46.59</b> |
| <b>- Excess (S\$)</b>               | <b>800.00</b>    | <b>800.00</b>    | <b>0.00</b>      | <b>0.00</b>  |
| <b>(S\$)</b>                        | <b>47,865.00</b> | <b>25,189.76</b> | <b>22,675.24</b> | <b>47.37</b> |
| <b>+ GST 7.00/7.00% (S\$)</b>       | <b>3,350.55</b>  | <b>1,763.28</b>  | <b>1,587.27</b>  | <b>47.37</b> |
| <b>Nett Amount (S\$)</b>            | <b>51,215.55</b> | <b>26,953.04</b> | <b>24,262.51</b> | <b>47.37</b> |

### INSPECTION

|                             |            |               |  |
|-----------------------------|------------|---------------|--|
| Date of Assignment:         | 13/05/2022 |               |  |
| Date Inspected:             | 10/05/2022 | Inspected At: | Premium Automobiles Pte Ltd (UBI)<br>55 Ubi Road 1<br>Singapore 408699 |
| Estimated Period of Repair: | 7.0 days   |               |  |

**Adjuster:** ADRIAN LING

**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

# REPAIR DETAILS

## Recommended Parts

| No. | Qty | Part No. Particulars                                    | Condition           | Repairer's   | Amount        |
|-----|-----|---|---------------------|--------------|---------------|
| 1   | 1   | *FRONT BUMPER   | Deformed            | 2,240.00 FS  | *2,240.00 FS  |
| 2   | 1   | *FRONT BUMPER RADIATOR GRILLE                           | Smashed             | 0.00 FS      | *- FS         |
| 3   | 2   | *FRONT BUMPER AIR GRILLE - LH / RH<br>(NPA)             | Not Necessary       | 0.00 FS      | *- FS         |
| 4   | 1   | *FRONT BUMPER FOAM                                      | Not Necessary       | 139.00 FS    | *- FS         |
| 5   | 1   | *FRONT BUMPER CARRIER                                   | Dented              | 899.00 FS    | *719.20 FS    |
| 6   | 1   | *FRONT BUMPER TOP COVER                                 | Deformed            | 143.00 FS    | *114.00 FS    |
| 7   | 1   | *CAUTION STICKER  | Necessary           | 16.00 FS     | *12.40 FS     |
| 8   | 1   | *A/C STICKER  | Necessary           | 9.00 FS      | *6.64 FS      |
| 9   | 2   | *FRONT BUMPER GUIDE SECTION - LH / RH                   | Not Necessary       | 82.00 FS     | *- FS         |
| 10  | 2   | *FRONT BUMPER BRACKET - LH / RH                         | Bent                | 508.00 FS    | *406.40 FS    |
| 11  | 1   | *FRONT BUMPER CARRIER BRACKET                           | Cracked             | 154.00 FS    | *122.80 FS    |
| 12  | 2   | *FRONT BUMPER SUPPORT - LH / RH                         | Damaged             | 64.00 FS     | *51.04 FS     |
| 13  | 4   | *RIVET  | Necessary           | 4.00 FS      | *2.88 FS      |
| 14  | 4   | *FRONT BUMPER PARKING AID SENSOR - INNER / OUTER        | Not Necessary       | 1,060.00 FS  | *- FS         |
| 15  | 4   | *FRONT BUMPER PARKING AID SENSOR SEAL RING              | Not Necessary       | 10.00 FS     | *- FS         |
| 16  | 1   | *SET FRONT BUMPER WIRING                                | Not Necessary       | 567.00 FS    | *- FS         |
| 17  | 2   | *HORN - LH / RH   | Not Necessary       | 273.00 FS    | *- FS         |
| 18  | 2   | *HORN BRACKET - LH / RH                                 | Not Necessary       | 66.00 FS     | *- FS         |
| 19  | 1   | *BONNET   | Dented              | 3,491.00 FS  | *2,792.80 FS  |
| 20  | 1   | *BONNET ATTACHMENT PARTS                                | Not Necessary       | 128.00 FS    | *- FS         |
| 21  | 2   | *BONNET HINGE - LH / RH                                 | Not Necessary       | 932.00 FS    | *- FS         |
| 22  | 3   | *BONNET IMPACT PROTECTION - LH / RH CENTER              | Necessary           | 93.00 FS     | *73.20 FS     |
| 23  | 1   | *BONNET SOUND ABSORBER                                  | Not Necessary       | 382.00 FS    | *- FS         |
| 24  | 1   | *BONNET BOWDEN CABLE - CENTER                           | Damaged             | 64.00 FS     | *50.56 FS     |
| 25  | 1   | *BONNET RELEASE LEVER                                   | Damaged             | 15.00 FS     | *11.84 FS     |
| 26  | 1   | *BONNET BOWDEN CABLE - CENTER                           | Not Necessary       | 64.00 FS     | *- FS         |
| 27  | 1   | *BONNET BOWDEN CABLE COVER                              | Not Necessary       | 11.00 FS     | *- FS         |
| 28  | 2   | *BONNET STRIKER - LH / RH                               | Not Necessary       | 112.00 FS    | *- FS         |
| 29  | 2   | *BONNET LOCK  | Not Necessary       | 455.00 FS    | *- FS         |
| 30  | 2   | *HEADLIGHT - LH / RH                                    | Cracked             | 16,832.00 FS | *13,465.60 FS |
| 31  | 2   | *HEADLIGHT LIFT CYLINDER - LH / RH                      | Not Necessary       | 434.00 FS    | *- FS         |
| 32  | 2   | *HEADLIGHT LIFT CYLINDER BRACKET - LH / RH              | Not Necessary       | 34.00 FS     | *- FS         |
| 33  | 1   | *HEADLIGHT LIFT CYLINDER CORRUGATED PIPE                | Not Necessary       | 100.00 FS    | *- FS         |
| 34  | 1   | *LOCK CARRIER   | Not Necessary       | 1,127.00 FS  | *- FS         |
| 35  | 2   | *LOCK CARRIER SUPPORT                                   | Not Necessary       | 85.00 FS     | *- FS         |
| 36  | 1   | *A/C CONDENSER  | Dented              | 546.00 FS    | *546.00 FS    |
| 37  | 1   | *A/C BRACKET  | Damaged             | 21.00 FS     | *16.32 FS     |
| 38  | 1   | *CHARGE AIR COOLER                                      | Not Necessary       | 654.00 FS    | *- FS         |
| 39  | 1   | *PRESSURE HOSE  | Not Necessary       | 413.00 FS    | *- FS         |
| 40  | 1   | *PRESSURE PIPE  | Not Necessary       | 496.00 FS    | *- FS         |
| 41  | 1   | *RADIATOR   | Not Necessary       | 1,010.00 FS  | *- FS         |
| 42  | 6   | *COOLANT  | Not Necessary       | 282.00 FS    | *- FS         |
| 43  | 1   | *RADIATOR FAN   | Not Necessary       | 2,483.00 FS  | *- FS         |
| 44  | 1   | *RADIATOR AIR GUIDE - LH / RH / UPPER / LOWER<br>(6PCS) | Cracked (4Pcs only) | 154.00 FS    | *85.84 FS     |
| 45  | 1   | *RADIATOR FAN RING                                      | Not Necessary       | 291.00 FS    | *- FS         |
| 46  | 1   | *LOWER NOISE INSULATION                                 | Not Necessary       | 640.00 FS    | *- FS         |
| 47  | 1   | *FRONT NO. PLATE  | Dented              | 60.00 FS     | *60.00 FS     |
| 48  | 1   | *SUNDRIES   | Necessary           | 350.00 FS    | *10.24 FS     |

F=Franchise part. S=SpcNett.

**Total Parts (\$\$) 37,993.00 20,787.76**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars   | Lab.Type | Repairer's       | Amount          |
|--------------------------------|---|----------|------------------|-----------------|
| <b>Labour Items</b>            |   |          |                  |                 |
| 1                              | TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE  | New      | 800.00           | 500.00          |
| 2                              | TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT PRESSURISE, VACUUM AND REGAS                   | New      | 1,700.00         | 480.00          |
| 3                              | TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHT. BONNET AND BOTH HEADLIGHT. POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED | New      | 4,800.00         | 2,250.00        |
| 4                              | TO APPLY PROTECTION FILM ON HEADLIGHT AND PAINT COATING AT AFFECTED AREA. (BY OWNER)  | New      | 200.00           | 200.00          |
| 5                              | TO RESPRAY FRONT BUMPER, BONNET AND HINGES  | New      | 2,500.00         | 1,100.00        |
| 6                              | TO CARRY OUT DIAGNOSTIC CHECK   | New      | 192.00           | 192.00          |
| 7                              | TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID                           | New      | 480.00           | 480.00          |
| <b>Gross Labour Cost (S\$)</b> |   |          | <b>10,672.00</b> | <b>5,202.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >