

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBH 3847M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SET RIM BEARING	NOT NECESSARY	70.00	-
1	FRONT BRAKE DISC ROTOR	BENT / DISTORTED	78.00	78.00
1	FRONT MUDGUARD	BROKEN	65.00	65.00
2	SET FORK, LEFT / RIGHT	BENT	680.00	680.00
1	BOTTOM CLAMP, STEERING STEM	BENT / DISTORTED	150.00	85.00
2	SET STEERING CON BEARING	NECESSARY	180.00	80.00
1	HANDLEBAR	BENT	120.00	120.00
1	FRONT BRAKE MASTER PUMP	SERVICEABLE	150.00	-
1	BRAKE LEVER	BROKEN	30.00	30.00
1	CLUTCH LEVER	SERVICEABLE	30.00	-
1	LAMPSTAY	BENT / DISTORTED	180.00	105.00
1	COWL HEAD	ABRADED	180.00	180.00
1	HEADLIGHT	GRAZED / BROKEN	450.00	299.00
1	SPEEDOMETER	BROKEN	380.00	220.00
1	LEFT SIDE MIRROR	SCRAPED	70.00	70.00
1	RIGHT SIDE MIRROR	ABRADED	70.00	70.00
1	TOP TANK COVER	GRAZED	68.00	68.00
1	RIGHT SIDE TANK COVER	GRAZED	120.00	120.00
1	LEFT SIDE TANK COVER	GRAZED / BROKEN	120.00	120.00
1	LEFT SIDE INNER COVER	BROKEN	78.00	78.00
1	LEFT SIDE OUTER COVER	ABRADED	78.00	78.00
1	RIGHT SIDE INNER COVER	NOT NECESSARY	78.00	-
1	RIGHT SIDE OUTER COVER	ABRADED	78.00	78.00
1	FRONT LEFT SIGNAL	BROKEN	80.00	45.00
1	LEFT SIDE ENGINE COVER	ABRADED	220.00	220.00
1	FRONT LEFT LOWER COVER	NOT NECESSARY	60.00	-
1	FRONT RIGHT LOWER COVER	NOT NECESSARY	60.00	-
1	SET GEAR LEVER PEDAL	BENT	150.00	85.00
1	SIDE STAND	SERVICEABLE	55.00	-
1	EXHAUST GUARD	ABRADED	120.00	75.00
1	TOP CLAMP	NOT NECESSARY	180.00	-

Report Ref No. CS3/ASM21007886/Rqy3e2-1

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-442.80	-304.90
			3,985.20	2,744.10
1	FRONT RIM (SN) (LOCAL REPAIR)	SCRATCHED	580.00	100.00
	LESS 10% DISCOUNT		-58.00	-
			522.00	100.00
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BOX RACK (SN)	SERVICEABLE	180.00	-
1	REAR BOX (SN)	ABRADED	450.00	350.00
1	BATTERY (SN)	NOT NECESSARY	98.00	-
1	LEFT SIDE ENGINE COVER GASKET (SN)	NECESSARY	28.00	15.00
1	ENGINE OIL (SN)	NECESSARY	34.00	20.00
1	SET HANDLEBAR END BALANCER (SN)	BENT / SCRAPED	40.00	20.00
1	FRONT WHEEL AXLE BOLT (SN)	BENT	35.00	15.00
			865.00	420.00
	<u>LABOUR</u>			
	TO CHECK WIRING.		30.00	20.00
	WORKMANSHIP.		600.00	400.00
	TOWING FEE. (2X).		80.00	35.00
			710.00	455.00
	GRAND TOTAL		6,082.20	3,719.10
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,950.00

Report Ref No. CS3/ASM21007886/Rqy3e2-1

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.