

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/TMI22004401/TQCN2**Date:** 31/05/2022REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MJ001706		
<b>Claimant Vehicle No :</b>	SHA4546R	<b>Insured Vehicle No :</b>	SLH9918J		
Date of Loss:	10/05/2022	Nature of Claim:	TP	Claim No:	M2202286

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHA4546R</b>	Engine No:	2ZRR926784
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Chassis No:	JTDKB3FU903539598
Reg. Date:	30/12/2016 (Man. Year: 2016)	Odometer:	768477 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Average

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,206.24	507.72	698.52	57.91
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	750.00	630.00	120.00	16.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>1,967.24</b>	<b>1,148.72</b>	<b>818.52</b>	<b>41.61</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>900.00</b>		
<b>(S\$)</b>	1,967.24	900.00	1,067.24	54.25
<b>+ GST 7.00/7.00% (S\$)</b>	137.71	63.00	74.71	54.25
<b>Nett Amount (S\$)</b>	<b>2,104.95</b>	<b>963.00</b>	<b>1,141.95</b>	<b>54.25</b>

INSPECTION

Date of Assignment:	11/05/2022	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	11/05/2022	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 30 May 2022)

**Parts:** 144      TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SHA4546R)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*REAR BUMPER ASSY	Repair	503.04 FL	-	*- FL
2	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	-	*22.00 FL
3	1		*REAR BUMPER BEAM	Not Necessary	378.32 FL	-	*- FL
4	1		*REAR BUMPER MLDG CENTRE	Deformed	654.96 FL	-	*654.96 FL
5	1		*REAR BUMPER MAT	Not Necessary	50.00 FL	-	*- FL
					<b>Sub Total (\$\$)</b>	<b>1,608.32</b>	<b>676.96</b>
					<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	402.08	169.24
					<b>Total Parts (\$\$)</b>	<b>1,206.24</b>	<b>507.72</b>

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	400.00	350.00
2	SPRAYPAINT	New	300.00	250.00
3	REMOVE/REFIX REVERSE SENSOR	New	50.00	30.00
Gross Labour Cost (\$\$)			750.00	630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >