

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22004405/EQCE2

Date: 07/09/2022

REFERENCE

Insured/Claimant:	PUVANESWARI SANDIRASEKARAN	Policy No:	721010932	
Date of Loss:	07/05/2022	Nature of Claim:	OD	Claim No: 4372634731SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMZ7626H	Engine No:	CVK084387
Make & Model:	AUDI A4, 2.0 SEDAN TFSI S-TRONIC (NAV) (A)	Chassis No:	WAUZZZF45KA087920
Reg. Date:	30/09/2019 (Man. Year: 2019)	Odometer:	26749 km
Colour:	Red		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$145,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Goodyear 5 mm	Rear Left Side:	Goodyear 5 mm
Front Right Side:	Goodyear 5 mm	Rear Right Side:	Goodyear 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	50,979.60	13,914.32	37,065.28	72.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	19,794.00	12,614.00	7,180.00	36.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	70,773.60	26,528.32	44,245.28	62.52
+ GST 7.00/7.00% (S\$)	4,954.15	1,856.98	3,097.17	62.52
Nett Amount (S\$)	75,727.75	28,385.30	47,342.45	62.52

INSPECTION

Date of Assignment:	11/05/2022		
Date Inspected:	11/05/2022	Inspected At:	Premium Automobiles Pte Ltd 24 Benoi Sector Singapore 629857
Estimated Period of Repair:	17.0 days		

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Crushed	1,429.60 FS	*1,429.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	612.00 FS	*- FS
3	1		*FRONT BUMPER AIR GUIDE - LH	Not Necessary	72.00 FS	*- FS
4	2		*FRONT BUMPER SECURING STRIP	Not Necessary	79.00 FS	*- FS
5	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	219.00 FS	*- FS
6	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	254.00 FS	*- FS
7	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Not Necessary	151.00 FS	*- FS
8	1		*FRONT BUMPER GUIDE SECTION - LH	Broken	41.00 FS	*32.24 FS
9	1		*FRONT BUMPER COVER	Not Necessary	143.00 FS	*- FS
10	1		*STICKER FOR SIGN CAUTION	Not Necessary	16.00 FS	*- FS
11	1		*STICKER FOR AIR CONDITIONER	Not Necessary	9.00 FS	*- FS
12	1		*FRONT FENDER - LH	Dented	861.00 FS	*688.80 FS
13	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	211.00 FS	*- FS
14	1		*FRONT FENDER CLOSING ELEMENT - LH	Necessary	81.00 FS	*64.24 FS
15	1		*FRONT FENDER CENTER BRACKET - LH	Necessary	41.00 FS	*32.72 FS
16	1		*FRONT FENDER BRACKET FOR DEFORMATION - LH	Necessary	55.00 FS	*44.00 FS
17	6		*FRONT FENDER POP RIVET	Necessary	23.00 FS	*18.24 FS
18	1		*FRONT FENDER REAR BRACKET - LH	Not Necessary	36.00 FS	*- FS
19	1		*FRONT FENDER UPPER BRACKET - LH	Not Necessary	37.00 FS	*- FS
20	1		*FRONT FENDER BRACE - LH	Dented	132.00 FS	*105.20 FS
21	1		*FRONT FENDER INSULATOR - LH	Not Necessary	37.00 FS	*- FS
22	1		*FRONT FENDER COVER - LH	Not Necessary	13.00 FS	*- FS
23	1		*FRONT WHEEL HOUSING LINER - LH	Crushed	260.00 FS	*208.00 FS
24	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	0.00 FS	*- FS
25	1		*FRONT WHEEL SPOILER - LH	Broken	82.00 FS	*65.12 FS
26	1		*FRONT END PLATE - LH	Not Necessary	39.00 FS	*- FS
27	1		*FRONT STONE CHIP GUARD - LH	Cut	57.00 FS	*45.28 FS
28	1		*FRONT FENDER LEDGE COVER LONG - LH	Necessary	35.00 FS	*27.52 FS
29	1		*FRONT FENDER LEDGE COVER SHORT - LH	Necessary	26.00 FS	*20.16 FS
30	1		*BONNET	Repair	3,425.00 FS	*- FS
31	1		*BONNET IMPACT PROTECTION - CENTER	Not Necessary	31.00 FS	*- FS
32	2		*BONNET IMPACT PROTECTION - LH / RH	Not Necessary	62.00 FS	*- FS
33	1		*FRONT DOOR - LH	Dented	3,431.00 FS	*2,744.80 FS
34	1		*FRONT OUTER SEAL - LH	Necessary	229.00 FS	*182.80 FS
35	1		*BONDING AGENT	Not Necessary	51.00 FS	*- FS
36	1		*CLEANING SOLUTION	Not Necessary	74.00 FS	*- FS
37	1		*APPLICATOR	Not Necessary	8.00 FS	*- FS
38	1		*FRONT DOOR ATTACHMENT PARTS - LH	Not Necessary	1,153.00 FS	*- FS
39	1		*FRONT DOOR CATCH - LH (NPA)	Not Necessary	0.00 FS	*- FS
40	1		*FRONT DOOR TRIM PLATE - LH	Repair	98.00 FS	*- FS
41	1		*FRONT DOOR HANDLE COVER CAP - LH	Repair	7.00 FS	*- FS
42	1		*FRONT DOOR HANDLE HOUSING - LH	Not Necessary	9.00 FS	*- FS
43	1		*FRONT EXTERIOR MIRROR MOUNTING - LH	Cut	1,201.00 FS	*960.80 FS
44	1		*FRONT WING MIRROR CAP - LH	Repair	308.00 FS	*- FS
45	1		*FRONT WING MIRROR GLASS - LH	Not Necessary	1,298.00 FS	*- FS
46	1		*FRONT WINDOW SLOT SEAL - LH	Not Necessary	344.00 FS	*- FS
47	1		*ASSEMBLY CARRIER	Not Necessary	2,096.00 FS	*- FS
48	1		*FRONT WISHBONE LINK - LH	Bent	605.00 FS	*483.60 FS
49	1		*FRONT SUSPENSION LINK - LH	Bent	1,057.00 FS	*845.60 FS
50	1		*FRONT CONTROL ARM - LH	Not Necessary	575.00 FS	*- FS
51	1		*FRONT CONTROL ARM REAR - LH	Not Necessary	575.00 FS	*- FS
52	1		*FRONT WHEEL BEARING HOUSING - LH	Bent	5,070.00 FS	*856.00 FS
53	1		*SWIVEL JOINT	Necessary	214.00 FS	*170.80 FS
54	1		*FRONT WHEEL HUB - LH	Necessary	498.00 FS	*398.00 FS
55	1		*FRONT BALL BEARING - LH	Necessary	273.00 FS	*218.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*FRONT SUSPENSION FORKS - LH	Bent	293.00 FS	*234.00 FS
57	2		*FRONT COUPLING ROD	Not Necessary	258.00 FS	*- FS
58	1		*FRONT DRIVE SHAFT	Not Necessary	2,999.00 FS	*- FS
59	1		*FRONT GAS SHOCK ABSORBER - LH	Not Necessary	332.00 FS	*- FS
60	1		*FRONT TRACK ROD	Not Necessary	109.00 FS	*- FS
61	1		*FRONT STEERING GEAR	Not Necessary	7,318.00 FS	*- FS
62	1		*LED HEADLIGHT - LH (NPA)	Not Necessary	0.00 FS	*- FS
63	1		*LIFT CYLINDER FOR HEADLIGHT WASHER SYSTEM	Not Necessary	231.00 FS	*- FS
64	1		*CORRUGATED PIPE FOR HEADLIGHT WASHER SYSTEM	Not Necessary	107.00 FS	*- FS
65	1		*CORRUGATED PIPE BRACKET	Not Necessary	7.00 FS	*- FS
66	1		*FRONT NOISE INSULATION	Not Necessary	640.00 FS	*- FS
67	1		*A/C PIPE	Bent	585.00 FS	*468.00 FS
68	1		*A/C PIPE BRACKET	Not Necessary	9.00 FS	*- FS
69	1		*A/C DISCHARGE HOSE	Not Necessary	381.00 FS	*- FS
70	1		*A/C SUCTION HOSE	Not Necessary	277.00 FS	*- FS
71	1		*A/C LINE	Not Necessary	186.00 FS	*- FS
72	1		*FRONT RIM - LH (NPA)	Repair	0.00 FS	*- FS
73	1		*FRONT TYRE - LH (80%)	Torn	350.00 FS	*280.00 FS
74	1		*REAR DOOR - LH	Dented	3,431.00 FS	*2,744.80 FS
75	1		*REAR DOOR OUTER SEAL - LH	Necessary	229.00 FS	*182.80 FS
76	1		*BONDING AGENT	Not Necessary	51.00 FS	*- FS
77	1		*CLEANING SOLUTION	Not Necessary	74.00 FS	*- FS
78	1		*APPLICATOR	Not Necessary	8.00 FS	*- FS
79	1		*REAR DOOR ATTACHMENT PARTS	Not Necessary	943.00 FS	*- FS
80	1		*REAR DOOR CATCH - RH (NPA)	Not Necessary	0.00 FS	*- FS
81	1		*REAR BUMPER	Repair	3,188.00 FS	*- FS
82	1		*REAR BUMPER SECURING STRIP	Not Necessary	249.00 FS	*- FS
83	2		*REAR BUMPER GUIDE SECTION - LH / RH	Not Necessary	52.00 FS	*- FS
84	1		*REAR BUMPER UPPER GUIDE SECTION - LH	Not Necessary	49.00 FS	*- FS
85	1		*REAR RIM - LH (NPA)	Not Necessary	0.00 FS	*- FS
86	1		*SUNDRIES	Necessary	700.00 FS	*183.20 FS
87	1		*STONE CHIP (Supplementary)	Necessary	180.00 FS	*180.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 50,979.60 13,914.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	250.00
3	TO REMOVE AND TRANSFER LHS FRONT DOOR AND RHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	700.00	560.00
4	TO RENEW LHS FRONT FENDER INNER PIPES. TO CARRY OUT VACUUM AND REGAS	New	280.00	280.00
5	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, LHS FRONT FENDER, LHS FRONT DOOR, LHS REAR DOOR AND LHS HEADLIGHT. REORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,200.00	2,000.00
6	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET, LHS FRONT DOOR, LHS WING MIRROR COVER, DOOR HANDLE AND LHS REAR DOOR	New	5,000.00	2,980.00
7	TO REMOVE AND RENEW LHS FRONT WHEEL SUSPENSION ASSY WITH SUBFRAME	New	2,400.00	2,400.00
8	TO RENEW LHS FRONT RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT	New	520.00	520.00
9	TO REMOVE AND TRANSFER REAR PARKING AND REAR LID KICK SENSOR	New	360.00	360.00
10	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR REAR LHS FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,400.00	750.00
11	TO RESPRAY REAR BUMPER AND LHS REAR FENDER	New	2,000.00	1,100.00
12	TO RENEW LHS REAR RIM	New	40.00	0.00
13	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE	New	280.00	0.00
14	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	New	384.00	384.00
15	TO RESPRAY LHS SILL PANEL. (Supplementary)	New	1,400.00	550.00
Gross Labour Cost (\$\$)			19,794.00	12,614.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >