

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22004406/DQY3E2

Date: 08/07/2022

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNW00011412100
Claimant Vehicle No : SLF3136Z **Insured Vehicle No :** SMH845H
Date of Loss: 08/05/2022 Nature of Claim: TP Claim No: SNM22D203150C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLF3136Z**
Make & Model: TOYOTA SIENTA, 1.5 (A) Engine No: 2NR8586982
Reg. Date: 22/08/2016 (Man. Year: 2016) Chassis No: NSP1707022504
Colour: Black Odometer: 77108 km
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55 R16 Rear Tyre Size: 195/55 R16
Front Left Side: Continental 5 mm Rear Left Side: Continental 5 mm
Front Right Side: Continental 5 mm Rear Right Side: Continental 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	33,556.99	5,120.95	28,436.04	84.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,320.00	1,060.00	6,260.00	85.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	40,876.99	6,180.95	34,696.04	84.88
Approved Total (Overridden) (\$\$)		4,800.00		
(\$\$)	40,876.99	4,800.00	36,076.99	88.26
+ GST 7.00/7.00% (\$\$)	2,861.39	336.00	2,525.39	88.26
Nett Amount (\$\$)	43,738.38	5,136.00	38,602.38	88.26

INSPECTION

Date of Assignment: 04/07/2022
Date Inspected: 11/05/2022 Inspected At: C S Ong Motor (HQ)
Block 10 Ang Mo Kio Ind Pk 2A
#02-16 AMK Autopoint
Singapore 568047
Estimated Period of Repair: 4.0 days

Adjuster: BRYAN TANI

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Jul 2022)
Parts:	M1-MPV	TOYOTA SIENTA 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLF3136Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Not Necessary	1,627.38 FL	*- FL
2	1		*BONNET LOCK	Not Necessary	342.85 FL	*- FL
3	1		*BONNET INSULATOR	Not Necessary	894.52 FL	*- FL
4	2		*BONNET HINGE LH / RH	Not Necessary	218.56 FL	*- FL
5	1		*BONNET STRIKER LOCK	Not Necessary	85.62 FL	*- FL
6	1		*HEAD LAMP LH	Cracked	7,690.20 FL	*2,490.20 FL
7	1		*HEAD LAMP LOWER BRACKET LH	Not Necessary	378.58 FL	*- FL
8	1		*FRONT BUMPER	Cut / Distorted	1,082.42 FL	*535.10 FL
9	1		*FRONT BUMPER SIDE RETAINER LH	Serviceable	188.48 FL	*- FL
10	1		*FRONT BUMPER GRILLE	Not Necessary	528.38 FL	*- FL
11	1		*FRONT BUMPER GRILLE BASE	Not Necessary	728.39 FL	*- FL
12	1		*FRONT BUMPER GRILLE CHROME MOULDING	Not Necessary	476.82 FL	*- FL
13	1		*FRONT BUMPER LOGO	Not Necessary	92.10 FL	*- FL
14	1		*FRONT BUMPER LOWER RUBBER	Not Necessary	210.48 FL	*- FL
15	1		*FRONT BUMPER FOG LAMP LH	Not Necessary	904.20 FL	*- FL
16	1		*FRONT BUMPER FOG LAMP GARNISH LH	Mtg Cracked	604.82 FL	*113.00 FL
17	1		*FRONT FENDER LH	Dented	2,196.40 FL	*551.00 FL
18	1		*FRONT FENDER INNER SHIELD LH	Torn	649.82 FL	*185.00 FL
19	1		*FRONT FENDER QUARTER GARNISH LH	Not Necessary	569.14 FL	*- FL
20	1		*FRONT BUMPER SPONGE	Not Necessary	284.57 FL	*- FL
21	1		*FRONT REINFORCEMENT BAR	Not Necessary	1,094.85 FL	*- FL
22	1		*FRONT SUPPORT PANEL	Not Necessary	1,984.52 FL	*- FL
23	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	328.75 FL	*- FL
24	1		*A/C CONDENSOR	Not Necessary	1,694.52 FL	*- FL
25	1		*A/C CONDENSOR HIGH PRESSURE PIPE	Not Necessary	849.10 FL	*- FL
26	1		*A/C CONDENSOR LOW PRESSURE PIPE	Not Necessary	342.57 FL	*- FL
27	1		*RADIATOR ASSY	Not Necessary	1,984.82 FL	*- FL
28	1		*RADIATOR FAN COMPLETE	Not Necessary	1,294.52 FL	*- FL
29	1		*FRONT WHEEL BEARING & HUB ASSY LH	Damaged	578.87 FL	*229.00 FL
30	1		*FRONT KNUCKLE ARM LH	Distorted	985.72 FL	*315.00 FL
31	1		*FRONT LOWER ARM LH	Distorted	782.84 FL	*325.00 FL
32	1		*FRONT ABSORBER LH	Distorted	699.72 FL	*385.00 FL
33	1		*FRONT STABILIZER LINK LH	Not Necessary	219.75 FL	*- FL
34	1		*FRONT STABILIZER BAR	Not Necessary	389.90 FL	*- FL
35	1		*FRONT TIE ROD LH	Not Necessary	284.40 FL	*- FL
36	1		*FRONT TIE ROD END LH	Not Necessary	367.72 FL	*- FL
37	1		*STEERING RACK & PINION ASSY	Not Necessary	2,785.74 FL	*- FL
38	1		*DRIVE SHAFT LH	Not Necessary	2,149.51 FL	*- FL
39	1		*SIDE MIRROR ASSY LH	Cracked	1,971.10 FL	*986.30 FL
40	1		*BONNET STICKER	Not fitted	500.00 FS	*- FS
41	1		*FRONT NO. PLATE & CASING	Not Necessary	100.00 FS	*- FS
42	1		*SPORT RIM	Cut	1,800.00 FS	*500.00 FS
43	1		*TYRE	Not Necessary	400.00 FS	*- FS
44	1		*BONNET INSULATOR CLIPS	Not Necessary	50.00 FS	*- FS
45	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
46	1		*FRONT GRILLE CLIPS	Not Necessary	50.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
48	1		*FRONT FENDER INNER SHIELD CLIPS	Necessary	50.00 FS	*15.00 FS
49	1		*COOLANT	Not Necessary	100.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$)					43,692.65	6,649.60
- List Item Discount on L Items 25.00/25.00% (\$)					10,135.66	1,528.65
Total Parts (\$)					33,556.99	5,120.95

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	3,000.00	400.00
2	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	3,000.00	400.00
3	TO TUFF COAT DAMAGED AREAS	New	200.00	20.00
4	TO RNR A/C CONDENSOR TO FACILITATE REPAIRS	New	200.00	0.00
5	TO RNR RADIATOR ASSY TO FACILITATE REPAIRS	New	200.00	0.00
6	TO RNR FRONT UNDERCARRIAGE TO FACILITATE REPAIRS	New	400.00	150.00
7	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	New	120.00	60.00
8	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
Gross Labour Cost (\$\$)			7,320.00	1,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >