



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SND 8114R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR FENDER RH	TO REPAIR SEE LABOUR	1,598.00	-
1	REAR BUMPER	DEFORMED	798.00	798.00
1	REAR BUMPER SIDE RETAINER	NOT NECESSARY	68.00	-
	LESS 25% DISCOUNT		-616.00	-199.50
			1,848.00	598.50
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REAR SPORTS RIM RH (SN)	NOT NECESSARY	800.00	-
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
			850.00	30.00
	<b><u>LABOUR</u></b>			
	TO CHECK ELECTRICAL WIRING.	NOT NECESSARY	50.00	-
	REMOVE AND REFIX REAR BUMPER SENSOR.		150.00	50.00
	CONDUCT WHEEL ALIGNMENT.	NOT NECESSARY	400.00	-
	ANTI RUST COAT.	NOT NECESSARY	150.00	-
	PANEL BEAT EFFECTED AREAS. INCLUSIVE OF THE REPAIR OF REAR FENDER RH.		600.00	200.00
	SPRAY PAINT ACCIDENT AREAS.		600.00	400.00
			1,950.00	650.00
<b>GRAND TOTAL</b>			<b>4,648.00</b>	<b>1,278.50</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,000.00</b>

Report Ref No. CS/AIS22004407/Any3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.