#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/ICS22004410/AVY3E2

07/07/2022 Date:

**REFERENCE** 

Handling Insurer: **ECICS Limited** 

Policy No:

**Claimant Vehicle** No:

SNE3509M

Insured Vehicle No: SMA9898H

Date of Loss: 07/05/2022 Nature of Claim: ΤP Claim No: DMCF2200047H/02/CT

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: **SNE3509M** 

TOYOTA PRIUS, 1.8 (A) Make & Model: Engine No: 2ZR2M88965

Reg. Date: JTDZS3EU00J067903 07/03/2022 (Man. Year: 2021) Chassis No:

Colour: Odometer: White 16879 km

**Engine Capacity:** 1798 cc Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price** 

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes No

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16 Front Left Side: Rear Left Side: Yokohama 6 mm Yokohama 6 mm Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		10,906.64	4,180.67	6,725.97	61.67
Miscellaneous Items		0.00	0.00	0.00	
Labour		3,830.00	2,420.00	1,410.00	36.81
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	14,736.64	6,600.67	8,135.97	55.21
	Approved Total (Overridden) (S\$)		5,250.00		
	(S\$)	14,736.64	5,250.00	9,486.64	64.37
	+ GST 7.00/7.00% (S\$)	1,031.56	367.50	664.06	64.37
	Nett Amount (S\$)	15,768.20	5,617.50	10,150.70	64.37

**INSPECTION** 

Date of Assignment: 11/05/2022

My Car Consultant Pte Ltd ( Jalan Lam Huat ) (HQ) Date Inspected: 11/05/2022 Inspected At:

60 Jalan Lam Huat, Carros Centre #05-21

Singapore 737869

Estimated Period of Repair: 7.0 days

Adjuster: **ADRIAN LING** Manager: **VERON CHEN** 

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

#### REPAIR DETAILS

### Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 04 Jul 2022)

Parts: 144 TOYOTA PRIUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SNE3509M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

Condition

Repairer's

**Amount** 

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

# Recommended Parts No. Qty Part No. Particulars

NO.	Qly	Part No.	Particulars	Condition	Repairers	Amount
1	1		*TAILGATE	Dented	1,598.00 FL	*929.00 FL
2	2		*TAILGATE LAMP	Not Necessary	918.00 FL	*- FL
3	1		*TAILGATE WEATHERSTRIP	Cut	212.00 FL	*212.00 FL
4	1		*TAILGATE LOGO	Not Necessary	95.50 FL	*- FL
5	1		*TAILGATE EMBLEM PRIUS T	Necessary	89.40 FL	*89.40 FL
6	1		*TAILGATE EMBLEM HYBRID	Necessary	82.30 FL	*82.30 FL
7	1		*TAILGATE DETECTOR	Not Necessary	321.00 FL	*- FL
8	1		*TAILGATE LOCK	Not Necessary	312.00 FL	*- FL
9	1		*TAILGATE WINDSCREEN MOULDING	Necessary	198.00 FL	*198.00 FL
10	1		*TAILGATE INNER TRIM BOARD	Not Necessary	459.00 FL	*- FL
11	1		*REAR BUMPER	Distorted	798.00 FL	*798.00 FL
12	1		*REAR BUMPER SIDE RETAINER	N/S Damaged	224.00 FL	*68.00 FL
13	1		*REAR BUMPER REINFORCEMENT	Dented	422.00 FL	*422.00 FL
14	2		*REAR BUMPER BRACKET	Not Necessary	228.00 FL	*- FL
15	1		*REAR BUMPER LIP	Deformed	728.90 FL	*412.00 FL
16	1		*REAR BUMPER REFLECTOR LH	Cracked	68.00 FL	*68.00 FL
17	1		*REAR BUMPER UNDER COVER LH	Not Necessary	321.00 FL	*- FL
18	1		*REAR FENDER LH	Repair	698.00 FL	*- FL
19	1		*REAR FENDER COWLING LH	Torn	198.20 FL	*198.20 FL
20	1		*REAR FENDER INNER TRIM (LOWER) LH	Not Necessary	612.00 FL	*- FL
21	1		*TAILLAMP LH	Smashed	694.00 FL	*596.00 FL
22	1		*TAILLAMP LOWER BRACKET LH	Cracked	82.00 FL	*82.00 FL
23	1		*TAILLAMP LOWER PANEL LH	Dented	314.00 FL	*314.00 FL
24	1		*REAR END PANEL	Dented	612.00 FL	*612.00 FL
25	1		*REAR END PANEL TOP GARNISH	Not Necessary	212.00 FL	*- FL
26	1		*REAR FLOOR PANEL	Not Necessary	1,151.00 FL	*- FL
27	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	398.00 FL	*- FL
28	1		*REAR FLOOR PANEL TOP SIDE SPONGE LH	Not Necessary	312.00 FL	*- FL
29	1		*REAR CHASSIS EXTENSION LH	Not Necessary	325.00 FL	*- FL
30	1		*REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
31	1		*REAR TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	80.00 FS	*-FS
32	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
33	1		*REAR WINDSCREEN INNER SEAL	Necessary	80.00 FS	*40.00 FS
34	1		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	50.00 FS	*-FS
35	1		*REAR REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
36	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	80.00 FS	*- FS
37	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
	-	part. S=SpcN	Vett. L=ListItemDisc.	- Nobbooking		
				Sub Total (S\$)	13,443.30	5,450.90
	- List Item Discount on L Items 20.00/25.00% (S\$)					1,270.23
				Total Parts (S\$)	10,906.64	4,180.67

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## **Recommended Labour**

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO CHECK REAR ELECTRICAL WIRING	New	150.00	30.00
2	TO REMOVE AND RENEW REVERSE SENSOR	New	150.00	50.00
3	TO REMOVE AND REFIT REAR GLASS	New	150.00	120.00
4	REMOVE AND RENEW REAR GARNISH / UPHOLSTERY	New	300.00	60.00
5	REMOVE AND RENEW TAILGATE MECHANISM	New	80.00	80.00
6	APPLY ANTI RUST ON AFFECTED AREAS	New	200.00	80.00
7	SPRAY PAINTING ON AFFECTED AREAS	New	1,400.00	1,000.00
8	PANEL BEATING ON AFFECTED AREAS	New	1,400.00	1,000.00
		Gross Labour Cost (S\$)	3,830.00	2,420.00
	Report was unsubmit	ted during this print-out.		

< END OF ESTIMATES >