7/4/22, 3:28 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22004413/UVY3M4

Date: 04/07/2022

REFERENCE

Date of Loss:

No:

Handling Insurer: China Taiping Insurance

(Singapore) Pte. Ltd.

Policy No: DMCVSNW00049972104

Claimant Vehicle

XD7509Z

Insured Vehicle XD8959B

J9Z

Nature of Claim: TP

Claim No: SNM22D202998/C02/CSC

DESCRIPTION & IDENTIFICATION OF VEHICLE

29/04/2022

Reg No: XD7509Z

 Make & Model:
 MITSUBISHI FV51JKM4RDEA, 12.9 D (M)
 Engine No:
 6M70457693

 Reg. Date:
 16/08/2013 (Man. Year: 2013)
 Chassis No:
 FV51JJA10147

 Colour:
 White/Blue
 Odometer:
 554994 km

Engine Capacity: 12882 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5 Rear Tyre Size: 295/80 R22.5 (D/D)
Front Left Side: HIFLY 6 mm Rear Left Side: HIFLY 6/66/6 mm
Front Right Side: HIFLY 6 mm Rear Right Side: HIFLY 6/66/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,350.00	1,806.00	2,544.00	58.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,450.00	780.00	670.00	46.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,800.00	2,586.00	3,214.00	55.41
Approved Total (Overridden) (S\$)		2,050.00		
(S\$)	5,800.00	2,050.00	3,750.00	64.66
+ GST 7.00/7.00% (S\$)	406.00	143.50	262.50	64.66
Nett Amount (S\$)	6,206.00	2,193.50	4,012.50	64.66

INSPECTION

Date of Assignment: 01/07/2022

Stytech Auto Pte Ltd (HQ)

Date Inspected: 26/05/2022 Inspected At: 2 Kaki Bukit Ave 2 #02-30, Kaki Bukit Autohub

Singapore 417921

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

7/4/22, 3:28 PM Adjuster Report

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 04 Jul 2022)

Parts: N/A MITSUBISHI FV51JKM4RDEA 12.9 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for XD7509Z)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RIGHT REAR DUMP BIN CANVAS RIM	Bent	450.00 FS	*450.00 FS
2	1		*RIGHT REAR DUMP BIN CANVAS	Torn	300.00 FS	*300.00 FS
3	1		*RIGHT REAR DUMP BIN WHEEL MUDGUARD	Repair	1,200.00 FS	*-FS
4	1		*RIGHT REAR FRONT RIM	Repair	600.00 FS	*-FS
5	1		*RIGHT REAR FRONT TYRE (LOCAL PURCHASE @\$380) (60%)	Cut	600.00 F	*228.00 F
6	1		*RIGHT REAR, REAR RIM	Bent	600.00 F	*600.00 F
7	1		*RIGHT REAR, REAR TYRE (LOCAL PURCHASE @\$380) (60%)	Punctured	600.00 F	*228.00 F
F=Fra	F=Franchise part. S=SpcNett.					
				Total Parts (S\$)	4,350.00	1,806.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount				
Lab	our Items							
1	CHECK WIRING }	New	50.00	0.00				
2	LABOUR TO FIXING }	New	600.00	480.00				
3	PAINT WORK	New	800.00	300.00				
		Gross Labour Cost (S\$)	1,450.00	780.00				
	Report was unsubmitted during this print-out.							

< END OF ESTIMATES >