

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 6893P

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR TAILGATE	TO REPAIR SEE LABOUR	1,475.00	-
2	REAR TAIL LAMP @\$292.00	BROKEN / CRACKED	584.00	584.00
1	REAR TAILGATE "DYNA"	NECESSARY	175.00	56.20
1	REAR EXHAUST PIPE	TO REPAIR SEE LABOUR	809.10	-
2	REAR EXHAUST MOUNTING @\$69.70	NOT NECESSARY	139.40	-
1	REAR TOOL BOX	BENT	460.00	460.00
1	REAR TOOL BOX HOLDER	NOT NECESSARY	393.00	-
1	REAR NUMBER PLATE PANEL	BENT	127.00	127.00
1	REAR LH REFLECTOR "LONG"	BROKEN	109.80	109.80
1	REAR LH REFLECTOR "ROUND"	SERVICEABLE	97.40	-
	LESS 25% DISCOUNT		-	-334.25
			4,369.70	1,002.75
	SPECIAL NETT ITEMS			
1	REAR TAIL LAMP PANEL (SN)	TO REPAIR SEE LABOUR	450.00	-
1	REAR NUMBER PLATE & BASE (SN)	BROKEN	48.00	40.00
1	REAR "70KM/H" STICKER (SN)	NECESSARY	15.00	10.00
1	REAR "12 PAX" STICKER (SN)	NECESSARY	15.00	10.00
			528.00	60.00
	<u>LABOUR</u>			
	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION.		60.00	20.00
	LABOR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS ETCS.INCLUSIVE OF THE REPAIR OF REAR TAILGATE,REAR EXHAUST PIPE AND REAR TAIL LAMP PANEL.		450.00	450.00
	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS.		500.00	480.00
			1,010.00	950.00
	GRAND TOTAL		5,907.70	2,012.75

Report Ref No. CS/AIS22004415/Uty3n2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		1,600.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/AIS22004415/Uty3n2

CHUA KANG SENG

Licensed Appraiser