

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	STRIDES AUTOMO	OTIVE SERVICES PTE LTD		Ref:	CS3/SMR22004416/Rty3m4	
	60 WOODLANDS I E4SINGAPORE 75	NDUSTRIAL PARK 7705		Date:	06/06/2022	
				Code:	SMR	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHB 593A	Veh. Inspected	t	JTY 3041	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	TAX/05/22/2018	Excess (\$)		0.00	
	Assign From	ASHLENE LEE	Assign Date		11/05/2022	
2.	2. Vehicle Particulars & Condition					
	Make & Model	YAMAHA	c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour		BLACK	
	Odometer	26336 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	100/80-17	MAXXIS		4 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	140/70-17	MAXXIS		4 mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND N/S BODY.					
5.	General Information					
	Accident Date	08/05/2022	Inspect Date /	Time	11/05/2022 (03:50 PM)	
	Survey held at	10 KAKI BUKIT ROAD 2 #01-36	(S 417868)			
	Repairer V MAPS MOTOR PTE LTD					
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000					
5b. Estimate Days of Repair						
	ESTIMATED NORM	MAL PERIOD FOR REPAIR:		4 Worki	ing Days	

Report Ref No. CS3/SMR22004416/Rty3m4

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

Automotive Assessor BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE