

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22004417/KPA3Q2**Date:** 29/11/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070134351
Claimant Vehicle No :	SLE983U	Insured Vehicle No :	GV1400Z
Date of Loss:	04/05/2022	Nature of Claim:	TP
		Claim No:	9305171133SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLE983U	Engine No:	2ZRR921772
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 (A)	Chassis No:	ZVW518020134
Reg. Date:	17/11/2016 (Man. Year: 2016)	Odometer:	68365 km
Colour:	Metallic Blue		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Michelin 9 mm	Rear Left Side:	Michelin 9 mm
Front Right Side:	Michelin 9 mm	Rear Right Side:	Michelin 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,135.58	10,607.60	5,527.98	34.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,940.00	2,590.00	1,350.00	34.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,075.58	13,197.60	6,877.98	34.26
Approved Total (Overridden) (S\$)		10,900.00		
(S\$)	20,075.58	10,900.00	9,175.58	45.71
+ GST 7.00/7.00% (S\$)	1,405.29	763.00	642.29	45.71
Nett Amount (S\$)	21,480.87	11,663.00	9,817.87	45.71
+ Car Rental (9.0 x S\$100.00/day) (S\$)		900.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		12,565.00		

INSPECTION

Date of Assignment:	06/05/2022	
Date Inspected:	06/05/2022	Inspected At: Alan's United Auto Pte Ltd (HQ) Blk 7 Sin Ming Industrial Estate, #01-76 Singapore 575642
Estimated Period of Repair:	7.0 days	

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Bent	1,159.90 FL	*1,159.90 FL
2	1		*TAIL GATE GLASS INNER SEAL	Necessary	107.10 FL	*107.10 FL
3	1		*TAIL GATE SPOILER	Serviceable	1,044.30 FL	*- FL
4	1		*TAIL GATE 3RD BRAKE LIGHT	Serviceable	203.40 FL	*- FL
5	1		*TAIL GATE LOWER GLASS	Shattered	688.80 FL	*688.80 FL
6	1		*TAIL GATE LOWER TRIM COVER	Mtg Cracked	605.20 FL	*605.20 FL
7	1		*TAIL GATE INNER TRIM COVER	Mtg Cracked	433.70 FL	*433.70 FL
8	1		*TAIL GATE RUBBER (50%)	Dented / Distorted	290.48 FS	*193.65 FS
9	1		*TAIL GATE INNER LOCK	Dented	495.40 FL	*452.10 FL
10	1		*TAIL GATE OUTER GARNISH	Cracked	685.70 FL	*685.70 FL
11	1		*TAIL GATE PRIUS EMBLEM	Necessary	72.10 FL	*72.10 FL
12	1		*TAIL GATE HYBRID EMBLEM	Necessary	66.40 FL	*66.40 FL
13	1		*TAIL GATE LOGO	Necessary	64.80 FL	*64.80 FL
14	2		*TAIL GATE NO .PLATE LAMP	Serviceable	184.40 FL	*- FL
15	2		*TAILLAMP	O/S Cracked / N/S Mtg Cracked	1,108.40 FL	*1,002.60 FL
16	2		*TAILLAMP SIDE GARNISH	Dented	131.40 FL	*131.40 FL
17	1		*REAR END PANEL	Bent	592.20 FL	*592.20 FL
18	1		*REAR PANEL TOP GARNISH	Distorted	233.80 FL	*233.80 FL
19	1		*SPARE TYRE PANEL	Repair	969.90 FL	*- FL
20	1		*SPARE TYRE TOP COVER	Deformed	526.60 FL	*526.60 FL
21	1		*N/S SPARE TYRE TOOL SPONGE	Cracked	460.60 FL	*460.60 FL
22	1		*O/S SPARE TYRE TOOL SPONGE	Cracked	460.60 FL	*460.60 FL
23	1		*REAR BUMPER FASCIA	Bent	693.30 FL	*485.60 FL
24	1		*REAR BUMPER SIDE (LOWER)	O/S Mtg Cracked	256.80 FL	*128.40 FL
25	1		*REAR BUMPER LOWER SPOILER	Bent	482.20 FL	*482.20 FL
26	1		*REAR LOWER SPOILER TOW COVER	Dented	32.30 FL	*32.30 FL
27	1		*REAR BUMPER REINFORCEMENT	Bent	326.60 FL	*326.60 FL
28	1		*REAR BUMPER CENTRE UNDER COVER	Cracked	255.40 FL	*255.40 FL
29	2		*REAR BUMPER SIDE UNDER COVER	Cracked	484.40 FL	*484.40 FL
30	2		*REAR BUMPER LAMP	Mtg Cracked	797.40 FL	*797.40 FL
31	1		*REAR BUMPER SIDE RETAINER	O/S Distorted	219.80 FL	*109.90 FL
32	2		*REAR BUMPER NUT & SCREW	Necessary	12.80 FL	*12.80 FL
33	1		*REAR EXHAUST SILENCER BOX	Repair	1,738.50 FL	*- FL
34	1		*REAR EXHAUST HEAT SEAL	Serviceable	238.50 FL	*- FL
35	1		*REAR O/S BLIND SPOT SENSOR BOX	Serviceable	2,234.10 FL	*- FL
36	1		*SET TAIL GATE CENTRE EMBLEM	Necessary	80.00 FS	*80.00 FS
37	1		*END PANEL TOP GARNISH CHROME	Buckled	120.00 FS	*120.00 FS
38	2		*REAR BUMPER PARKING SENSOR (CTR)	Dented / Shorted	400.00 FS	*400.00 FS
39	2		*RR BUMPER SIDE PARKING SENSOR	Shorted	400.00 FS	*400.00 FS
40	1		*SET REAR BUMPER CLIP	Necessary	40.00 FS	*40.00 FS
41	1		*REAR W/S GLASS SEALANT	Necessary	100.00 FS	*80.00 FS
42	1		*REAR NO PLATE WITH CASING	Dented	50.00 FS	*45.00 FS
43	1		*TAIL GATE OPEN SWITCH ASSY	Jammed	800.00 FS	*800.00 FS
44	1		*REAR BUMPER TOP CHROME	Bent	155.00 FS	*155.00 FS
45	1		*REAR BUMPER LOWER CHROME	Cracked	150.00 FS	*150.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	20,652.28	13,322.25
- List Item Discount on L Items 25.00/25.00% (\$\$)	4,516.70	2,714.65
Total Parts (\$\$)	16,135.58	10,607.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & RENEW REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST	New	200.00	180.00
2	TO REMOVE ROOF LINING FRONT AND REAR SEATS ,TRIM BOARD AND CARPET	New	180.00	80.00
3	TO APPLY UNDERSEALING	New	100.00	30.00
4	TO REMOVE AND RENEW EXHAUST SILENCER BOX	New	60.00	0.00
5	TO PUTTY AND SPRAY REPLACED PARTS	New	1,600.00	1,400.00
6	TO REMOVE CUT -OUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW ABOVE PARTS	New	1,800.00	900.00
Gross Labour Cost (\$\$)			3,940.00	2,590.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >