



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YN 5278M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	TAIL LAMP RH	CRACKED	230.91	230.91
1	TAIL LAMP BRACKET	BENT	98.00	98.00
1	REAR RUBBER STOPPER RH	SERVICEABLE	120.00	-
1	REAR RUBBER STOPPER BRACKET	BENT	90.00	90.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	867.10	-
	LESS 10% DISCOUNT		-140.60	-
	LESS 25% DISCOUNT		-	-104.73
			1,265.41	314.18
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER (SN) }	BENT	1,200.00	700.00
2	REAR BUMPER BRACKET @\$150.00 (SN) }		300.00	-
			1,500.00	700.00
	<u>LABOUR</u>			
	TO CHECK WIRING SYSTEM.		80.00	20.00
	TO TUFF COAT AFFECTED AREAS.	NOT NECESSARY	180.00	-
	TO RESPRAY AFFECTED AREAS.		750.00	500.00
	TO RENEW DAMAGED PARTS, STRAIGHTEN & REPAIR REAR RH TAIL GATE, TAIL GATE PILLAR, RH BODY PANEL LOWER MEMBER AND ALIGNED ALL PARTS. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		750.00	500.00
			1,760.00	1,020.00
	GRAND TOTAL		4,525.41	2,034.18
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,600.00

Report Ref No. CS/SMR22004421/Uvy3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.