



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: JANICE KOH			Ref: CS3/ASM22004422/Gty3e2 Date: 16/06/2022 Code: ASM	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHA 4254H	Veh. Inspected	SJN 2804S
	Policy No.		Coverage (\$)	0.00
	Claim No.	S2M040PH	Excess (\$)	0.00
	Assign From	JANICE KOH	Assign Date	11/05/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA VIOS G	c.c	1497
	Engine No.	HIDDEN	Year of Reg.	2009
	Chassis No.	MR053HY9305101663	Colour	GREY
	Odometer	318818 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/60 R15	TOURADOR	6 mm
	L/H Front Tyre	185/60 R15	TOURADOR	6 mm
	R/H Rear Tyre	185/60 R15	TOURADOR	6 mm
	L/H Rear Tyre	185/60 R15	TOURADOR	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
5. General Information				
	Accident Date	09/05/2022	Inspection Date	12/05/2022
	Survey held at	M.S LLH 1, KAKI BUKIT AVENUE 6 #01-67 AUTOBAY@KAKI BUKIT SINGAPORE 417883		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	