### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/FWD22004424/AVY3E2

26/05/2022 Date:

**REFERENCE** 

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2022-00000810

**Claimant Vehicle** SMS8459D Insured Vehicle No: **SLE3395Y** 

No:

Date of Loss: 08/05/2022 Nature of Claim: TP Claim No: 1202200005680

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SMS8459D

Make & Model: HONDA SHUTTLE, 1.5 (A) L15B6024047 Engine No: Reg. Date: Chassis No: 18/03/2020 (Man. Year: 2019) GK82103487 Colour: Odometer: 17881 km Red

**Engine Capacity:** 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price** 

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes No

CONDITION OF TYRES

Front Tyre Size: 205/50 R16 Rear Tyre Size: 205/50 R16 Front Left Side: Rear Left Side: Windforce 6 mm Windforce 6 mm Front Right Side: Windforce 6 mm Rear Right Side: Windforce 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		7,970.60	4,731.36	3,239.24	40.64
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,300.00	1,570.00	730.00	31.74
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	10,270.60	6,301.36	3,969.24	38.65
	Approved Total (Overridden) (S\$)		5,000.00		
	Nett Amount (S\$)	10,270.60	5,000.00	5,270.60	51.32

**INSPECTION** 

Date of Assignment: 11/05/2022

11/05/2022 Inspected At: Date Inspected:

1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY

JEC AUTO SERVICE PTE LTD (HQ)

Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: **ADRIAN LING** Manager: **VERON CHEN** 

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

# **REPAIR DETAILS**

### Reference

Part Source: (Last Synchronised: 26 May 2022)

Parts: N/A HONDA SHUTTLE 1.5 (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMS8459D)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,050.00 F	*1,050.00 FL
2	1		*FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
3	1		*FRONT BUMPER SIDE HOLDER RH	Damaged	38.50 F	*38.50 FL
4	1		*FRONT BUMPER SIDE LAMP RH	Not Necessary	245.90 F	*- FL
5	1		*FRONT BUMPER SIDE LAMP COVER RH	Not Necessary	66.40 F	*- FL
6	1		*HEADLAMP RH	Cut	2,250.40 F	*2,250.40 FL
7	1		*HEADLAMP LOWER BRACKET RH	Cracked	85.50 F	*85.50 FL
8	1		*FRONT GRILLE	Not Necessary	363.40 F	*- FL
9	1		*FRONT GRILLE LOGO	Not Necessary	65.40 F	*- FL
10	1		*FRONT GRILLE CLIPS	Not Necessary	20.00 FS	*-FS
11	1		*FRONT RH FENDER	Dented	645.90 F	*645.90 FL
12	1		*FRONT RH FENDER EXTENSION PANEL	Repair	485.20 F	*- FL
13	1		*FRONT RH FENDER INNER SHIELD	Torn	189.30 F	*189.30 FL
14	1		*FRONT RH FENDER INNER SHIELD CLIPS	Necessary	30.00 FS	*30.00 FS
15	1		*FRONT RH WHEEL RIM	Cut	800.00 FS	*480.00 FS
16	1		*FRONT RH TYRE	Not Necessary	280.00 FS	*-FS
17	1		*FRONT RH LOWER ARM	Bent	321.80 F	*321.80 FL
18	1		*FRONT RH SHOCK ABSORBER	Not Necessary	345.10 F	*- FL
19	1		*FRONT RH KNUCKLE ARM	Damaged	363.60 F	*363.60 FL
20	1		*FRONT RH WHEEL HUB C/W BEARING	Damaged	294.20 F	*294.20 FL
F=Fra	ınchise	part. S=SpcN	ett. L=ListItemDisc.			
				Sub Total (S\$)	7,970.60	5,779.20
			- List Item Discount on	L Items 0.00/20.00% (S\$)	0.00	1,047.84
				Total Parts (S\$)	7,970.60	4,731.36
			Report was unsubmitted duri	ng this print-out.		

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# **Recommended Labour**

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	800.00	600.00
2	SPRAY PAINTING	New	800.00	600.00
3	WIRING	New	50.00	30.00
4	TO SPRAY TUFF COAT	New	150.00	40.00
5	TO REMOVE FRONT UNDERCARRIAGE	New	350.00	220.00
6	TO PERFORM WHEEL ALIGNMENT	New	150.00	80.00
		Gross Labour Cost (S\$)	2,300.00	1,570.00
	Report was u	unsubmitted during this print-out.		

< END OF ESTIMATES >