

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22004425/UTY3Q2**Date:** 26/05/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00024062200		
Claimant Vehicle No :	SLW3582D	Insured Vehicle No :	SLX2640X		
Date of Loss:	08/05/2022	Nature of Claim:	TP	Claim No:	SNM22D203147/C02/THAMYL

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	SLW3582D	Engine No:	HR12276943B
Make & Model:	NISSAN NOTE, 1.2 (A)	Chassis No:	JN1TAAE12Z0980226
Reg. Date:	08/02/2018 (Man. Year: 2017)	Odometer:	37849 km
Colour:	White		
Engine Capacity:	1198 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	10,956.30	3,822.57	7,133.73	65.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,550.00	2,370.00	1,180.00	33.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>14,506.30</b>	<b>6,192.57</b>	<b>8,313.73</b>	<b>57.31</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	1,015.44	433.48	581.96	57.31
<b>Nett Amount (\$\$)</b>	<b>15,521.74</b>	<b>6,626.05</b>	<b>8,895.69</b>	<b>57.31</b>

**INSPECTION**

Date of Assignment:	11/05/2022		
Date Inspected:	11/05/2022	Inspected At:	Tan Lim Motor Pte Ltd (Defu) 1 Defu Lane 6 Singapore 539365
Estimated Period of Repair:	6.0 days		

**Adjuster:** MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 26 May 2022)
<b>Parts:</b>	144	NISSAN NOTE 1.2 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLW3582D)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	433.80 F	*425.90 FN
2	1		*FRONT BUMPER TOW COVER	Not Necessary	38.50 F	*- FN
3	2		*FRONT BUMPER FOG LAMP TRIM	Not Necessary	197.40 F	*- FN
4	1		*SET FRONT BUMPER CLIP	Necessary	50.00 F	*30.00 FN
5	1		*FRONT BUMPER UNDER PLASTIC	Twisted / Torn	416.30 F	*416.30 FN
6	1		*FRONT BUMPER SPONGE	Torn	240.50 F	*160.80 FN
7	1		*FRONT BUMPER REINFORCEMENT	Bent	420.00 F	*411.80 FN
8	2		*FRONT BUMPER SIDE RETAINER	Bent	93.20 F	*93.20 FN
9	1		*FRONT GRILLE	Cracked	332.10 F	*308.10 FN
10	1		*FRONT GRILLE TOP GARNISH	Repeated	350.80 F	*- FN
11	1		*FRONT GRILLE LOGO	Not Necessary	71.40 F	*- FN
12	1		*FRONT AIR GUIDE	Distorted	116.00 F	*116.00 FN
13	2		*FRONT HEADLAMP	Holder Cracked	3,552.00 F	*1,155.60 FN
14	2		*FRONT FENDER	Repair	1,197.80 F	*- FN
15	1		*FRONT BONNET	Repair	923.60 F	*- FN
16	1		*FRONT SUPPORT GUIDE	Not Necessary	83.90 F	*- FN
17	1		*FRONT SUPPORT PANEL	Repair	365.30 F	*- FN
18	1		*RADIATOR ASSEMBLY	Not Necessary	531.10 F	*- FN
19	1		*AIR CON CONDENSER ASSEMBLY	Not Necessary	370.00 F	*- FN
20	10		*FRONT FENDER INNER SHIELD CLIP	Not Necessary	43.00 F	*- FN
21	1		*O/S FRONT CHASSIS BRACKET	Bent	371.10 F	*371.10 FN
22	1		*N/S FRONT CHASSIS BRACKET	Bent	371.10 F	*371.10 FN
23	1		*GRILLE TOP GARNISH	Missing	304.40 F	*304.40 FN
24	1		*RADIATOR TOP SEAL	Necessary	83.00 F	*83.00 FN

F=Franchise part. N=NettItemDisc.

<b>Sub Total (\$\$)</b>	<b>10,956.30</b>	<b>4,247.30</b>
<b>- Nett Item Discount on N Items 0.00/10.00% (\$\$)</b>	0.00	424.73

<b>Total Parts (\$\$)</b>	<b>10,956.30</b>	<b>3,822.57</b>
---------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PUTTY AND SPRAY PAINTING FRONT OF THE AFFECTED PORTION	New	1,200.00	900.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTEN FRONT OF THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	1,600.00	1,100.00
3	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	80.00	20.00
4	TO RUST-PROOFING OF THE AFFECTED AREAS	New	150.00	0.00
5	TO PLACE VEHICLE ON JIG BENCH TO OBTAIN CROSS AND PARALLEL MEASUREMENT AND CORRECT TO MANUFACTURER SPECIFICATION WITH HYDRAULIC PNEUMATIC JACK	New	250.00	250.00
6	TO DISMANTLE AIR-CON ASSY ,REMOVE AND RENEWAL OF PARTS ,VACUUM AND CHARGE -IN GAS	New	120.00	100.00
7	TO TOP UP COOLANT	New	150.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,550.00</b>	<b>2,370.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >