

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22004431/ANY3E2

Date: 07/07/2022

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00147502100
Claimant Vehicle No : SKZ2283U **Insured Vehicle No :** SJN108G
Date of Loss: 08/05/2022 Nature of Claim: TP Claim No: SNM22D203158/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKZ2283U**
Make & Model: BMW 528I, 2.0 (A) Engine No: B2190892N20B20A
Reg. Date: 30/04/2015 (Man. Year: 2014) Chassis No: WBA5A52000D823644
Colour: Grey Odometer: 68837 km
Engine Capacity: 1997 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 265/30R19 Rear Tyre Size: 265/30R19
Front Left Side: Winrun 6 mm Rear Left Side: Winrun 6 mm
Front Right Side: Winrun 6 mm Rear Right Side: Winrun 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,212.55	5,972.80	7,239.75	54.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,980.00	810.00	2,170.00	72.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,192.55	6,782.80	9,409.75	58.11
Approved Total (Overridden) (S\$)		5,400.00		
(S\$)	16,192.55	5,400.00	10,792.55	66.65
+ GST 7.00/7.00% (S\$)	1,133.48	378.00	755.48	66.65
Nett Amount (S\$)	17,326.03	5,778.00	11,548.03	66.65

INSPECTION

Date of Assignment: 11/05/2022
Date Inspected: 11/05/2022 Inspected At: My Car Consultant Pte Ltd (Jalan Lam Huat) (HQ)
60 Jalan Lam Huat, Carros Centre #05-21
Singapore 737869
Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Jul 2022)
Parts:	143	BMW 528i 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKZ2283U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER RH	Not Necessary	1,358.00 FL	*- FL
2	1		*FRONT FENDER TOP GARNISH RH	Not Necessary	356.00 FL	*- FL
3	1		*FRONT FENDER COWLING	Not Necessary	212.20 FL	*- FL
4	1		*FRONT GRILLE	O/S Cut	996.00 FL	*235.00 FL
5	1		*FRONT GRILLE BASE	Torn	589.00 FL	*325.00 FL
6	1		*FRONT BUMPER SIDE BRACKET	Not Necessary	159.00 FL	*- FL
7	1		*FRONT BUMPER	Deformed	1,899.00 FL	*1,355.00 FL
8	1		*FRONT BUMPER TOP RUBBER	Not Necessary	120.00 FL	*- FL
9	1		*FRONT BUMPER SPONGE	Not Necessary	398.80 FL	*- FL
10	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	897.00 FL	*- FL
11	1		*FRONT BUMPER LOWER SIDE GRILLE RH	Cracked	112.00 FL	*112.00 FL
12	1		*FRONT BUMPER CENTER LOWER GRILLE	Cracked	325.00 FL	*325.00 FL
13	1		*FRONT BUMPER FOG LAMP RH	Not Necessary	541.00 FL	*- FL
14	2		*FRONT SENSOR	Damaged	642.00 FL	*642.00 FL
15	1		*HEAD LAMP LOWER GARNISH	Not Necessary	218.00 FL	*- FL
16	1		*HEAD LAMP RH	Cut	3,985.00 FL	*2,980.00 FL
17	1		*HEAD LAMP LOWER BRACKET	Cracked	258.00 FL	*185.00 FL
18	1		*HEADLAMP NOZER COVER	Missing	78.00 FL	*78.00 FL
19	1		*HEAD LAMP NOZER	Cracked	385.00 FL	*255.00 FL
20	10		*FRONT BUMPER CLIP	Necessary	65.00 FS	*30.00 FS
21	1		*FRONT FENDER SEALANT	Not Necessary	80.00 FS	*- FS
22	10		*FRONT FENDER COWLING CLIP	Not Necessary	65.00 FS	*- FS
23	1		*FRONT NUMBER PLATE	Cut	150.00 FS	*100.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,889.00	6,622.00
- List Item Discount on L Items 5.00/10.00% (\$\$)	676.45	649.20
Total Parts (\$\$)	13,212.55	5,972.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	New	800.00	250.00
2	TO SPRAY PAINT AFFECTED AREA	New	800.00	450.00
3	TUFF COAT	New	200.00	30.00
4	WIRING CHECK	New	150.00	30.00
5	ADJUST AND FOCUS FRONT LIGHTING SYSTEM. PERFORM HEADLAMP ADJUSTMENT TO POSITION	New	380.00	50.00
6	DISMENTLE AND REPLACE A/C CONDENSER ASSY. REFILL, RECHARGE A/C REFRIGERANT GAS AND PERFORM PRESSURE TEST	New	200.00	0.00
7	REMOVE AND INSTALL RADIATOR ASSY. PERFORMED RADIATOR PRESSURE TEST	New	150.00	0.00
8	REFOCUS AND PROGRAMMING HEADLAMP BEAM	New	300.00	0.00
Gross Labour Cost (\$\$)			2,980.00	810.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >