

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	LONPAC INSURAN	_	Ref:	CS3/LPC22004435/Bty3e2		
	300 BEACH ROAD			Date:	02/06/2022	
	#17-04/07 THE CO	NCOURSESINGAPORE 199555		Code:	I PC2	
1.		Policy Particulars				
1.	Insured Veh.	XE 2621J	Veh. Inspected	CLAI	SLM 6702H	
		AL 20213	<u> </u>		0.00	
	Policy No.	22/22/VC00/025777	Coverage (\$)		0.00	
	Claim No.		Excess (\$)			
	Assign From	GERALD POH	Assign Date		11/05/2022	
2. Vehicle Particulars & Condition						
	Make & Model	HONDA VEZEL 1.5S	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2017	
	Chassis No.	RU11117549	Colour		BLUE	
	Odometer	105167 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	215/55 R17	KUMHO		5 mm	
	L/H Front Tyre	215/55 R17	KUMHO		5 mm	
	R/H Rear Tyre	215/55 R17	KUMHO		5 mm	
	L/H Rear Tyre	215/55 R17	KUMHO		5 mm	
4. Description of Damages						
	THE VEHICLE SUS	STAINED DAMAGES AT THE O/S BODY.				
5.	5. General Information					
	Accident Date	09/05/2022	Inspect Date / T	ime	12/05/2022 ( 01:23 PM )	
	Survey held at	SIN HENG LONG MOTOR WORK				
		BLK 5032 ANG MO KIO INDUSTRIAL PARK 2 #01-287/305 SINGAPORE 569535				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					

Report Ref No. CS3/LPC22004435/Bty3e2

Inspected By

Um

LIM TEOW GUAN

**Automotive Assessor** 

L

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser