

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22004439/DQY3Q2**Date:** 19/09/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00026052201

Claimant Vehicle No : SMH2325D **Insured Vehicle No :** YP8434Z

Date of Loss: 11/05/2022 Nature of Claim: TP Claim No: SNM22D203232/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMH2325D**

Make & Model: HONDA FIT, 1.3 (A) Engine No: LEB1441064

Reg. Date: 16/01/2019 (Man. Year: 2018) Chassis No: GP51334239

Colour: Blue Odometer: 71157 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/45 R17 Rear Tyre Size: 205/45 R17

Front Left Side: Goodyear 5 mm Rear Left Side: Goodyear 5 mm

Front Right Side: Goodyear 5 mm Rear Right Side: Goodyear 5 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,416.48	3,644.22	12,772.26	77.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,250.00	1,470.00	4,780.00	76.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	22,666.48	5,114.22	17,552.26	77.44
Approved Total (Overridden) (\$\$)		4,000.00		
(\$\$)	22,666.48	4,000.00	18,666.48	82.35
+ GST 7.00/7.00% (\$\$)	1,586.65	280.00	1,306.65	82.35
Nett Amount (\$\$)	24,253.13	4,280.00	19,973.13	82.35

INSPECTION

Date of Assignment: 13/05/2022

Date Inspected: 11/05/2022 Inspected At: JWG International Pte Ltd (HQ)
Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK
AutoPoint
Singapore 568047

Estimated Period of Repair: 4.0 days

Adjuster: BRYAN TANI**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Sep 2022)
Parts:	144	HONDA FIT 1.3 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMH2325D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,102.00 FL	*962.80 FL
2	1		*TAILGATE WINDSCREEN MOULDING	Necessary	201.50 FL	*138.00 FL
3	1		*TAILGATE CENTER GARNISH	Not Necessary	301.20 FL	*- FL
4	1		*TAILGATE HONDA LOGO	Not Necessary	55.00 FL	*- FL
5	1		*TAILGATE HYBRID EMBLEM	Necessary	92.00 FL	*92.00 FL
6	2		*TAILGATE DAMPER LH/RH	Not Necessary	645.80 FL	*- FL
7	1		*TAILGATE INNER TRIM BOARD	Mtg Cracked	429.30 FL	*341.80 FL
8	1		*TAILGATE WEATHERSTRIP	Cut / Necessary	331.20 FL	*148.20 FL
9	1		*SET TAILGATE STOPPERS	Not Necessary	20.00 FL	*- FL
10	1		*TAILGATE LOCK	Damaged	342.40 FL	*180.65 FL
11	1		*TAILGATE SWITCH	Not Necessary	442.30 FL	*- FL
12	1		*TAILGATE STRIKER LOCK	Not Necessary	109.30 FL	*- FL
13	1		*TAILGATE INNER HANDLE	Not Necessary	99.80 FL	*- FL
14	2		*TAILGATE NO PLATE LAMP LH/RH	Not Necessary	190.00 FL	*- FL
15	2		*TAILGATE LAMP LH/RH	Not Necessary	591.60 FL	*- FL
16	2		*TAIL LAMP LH/RH	Scratched / Mtg Cracked	984.80 FL	*731.00 FL
17	2		*TAIL LAMP PANEL LH/RH	Not Necessary	803.60 FL	*- FL
18	2		*TAIL LAMP LOWER BRACKET LH/RH	Not Necessary	203.60 FL	*- FL
19	1		*REAR BUMPER	Distorted	659.40 FL	*592.77 FL
20	2		*REAR BUMPER SIDE RETAINER LH/RH	Serviceable	133.80 FL	*- FL
21	1		*REAR BUMPER CENTER GARNISH	Mtg Cracked	398.70 FL	*146.90 FL
22	2		*REAR BUMPER REFLECTOR LH/RH	Not Necessary	219.60 FL	*- FL
23	1		*REAR BUMPER REFLECTOR GARNISH LH/RH	O/SNot Necessary/N/SMtgCracked	419.60 FL	*75.20 FL
24	1		*REAR BUMPER LOWER LID	Not fitted	498.50 FL	*- FL
25	1		*REAR END PANEL	Dented	784.50 FL	*468.50 FL
26	1		*REAR END PANEL TOP GARNISH	Not Necessary	295.30 FL	*- FL
27	1		*SPARE WHEEL PANEL	Not Necessary	994.80 FL	*- FL
28	2		*SPARE WHEEL QUARTER PANEL LH/RH	Not Necessary	985.40 FL	*- FL
29	1		*SPARE WHEEL PANEL TOP BOARD	Not Necessary	599.00 FL	*- FL
30	1		*SPARE WHEEL PANEL TOOL BOX	Not Necessary	398.00 FL	*- FL
31	2		*REAR FENDER LH /RH	Not Necessary	2,659.40 FL	*- FL
32	2		*REAR FENDER INNER TRIM LH/RH	Not Necessary	985.60 FL	*- FL
33	2		*REAR FENDER AIR DUCT LH/RH	Not Necessary	198.00 FL	*- FL
34	2		*REAR FENDER QUARTER GLASS MOULDING LH/RH	Not Necessary	337.60 FL	*- FL
35	1		*REAR BUMPER SPONGE LH	Broken	158.00 FL	*88.10 FL
36	1		*REAR KEYLESS SENSOR	Mtg Broken	350.00 FL	*95.60 FL
37	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
38	1		*REAR WINDSCREEN DAMPING SEAL	Not Necessary	50.00 FS	*- FS
39	1		*TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*15.00 FS
40	1		*TAILGATE CENTER GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
41	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
42	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*40.00 FS
43	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS

Report was unsubmitted during this print-out.

9/19/22, 3:09 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*SPARE WHEEL PANEL SEALANT	Not Necessary	80.00 FS	*- FS
45	1		*REAR FENDER SEALANT	Not Necessary	80.00 FS	*- FS
46	1		*REAR FENDER INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
47	1		*REAR FENDER QUARTER GLASS SEALANT	Not Necessary	80.00 FS	*- FS
48	1		*REAR FENDER QUARTER GLASS DAMPING SEAL	Not Necessary	30.00 FS	*- FS
49	1		*REAR NO PLATE & CASING	Not Necessary	100.00 FS	*- FS
50	1		*REVERSE SENSOR	Damaged	300.00 FS	*220.00 FS
51	1		*REVERSE CAMERA	Not Necessary	600.00 FS	*- FS
52	1		*FEET EMBLEM	Necessary	100.00 FS	*30.00 FS
53	1		*PAW EMBLEM	Necessary	200.00 FS	*30.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					Sub Total (\$\$)	20,020.60 4,456.52
					- List Item Discount on L Items 20.00/20.00% (\$\$)	3,604.12 812.30
					Total Parts (\$\$)	16,416.48 3,644.22
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ALL INTERIOR UPHOLSTERY ITEMS TO FACILITATE REPAIRS	New	400.00	80.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,000.00	500.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,000.00	600.00
4	TO TUFF COAT DAMAGED AREAS	New	300.00	40.00
5	TO RNR TAILGATE MECHANISM TO FACILITATE REPAIRS	New	200.00	60.00
6	TO RNR REAR BUMPER SENSOR TO FACILITATE REPAIRS	New	150.00	40.00
7	TO RNR TAILGATE WINDSCREEN TO FACILITATE REPAIRS	New	300.00	120.00
8	TO RNR REAR FENDER QUARTER GLASS TO FACILITATE REPAIRS	New	200.00	0.00
9	TO RNR REVERSE CAMERA TO FACILITATE REPAIRS	New	100.00	0.00
10	TO RNR FUEL TANK FILLER PIPE TO FACILITATE REPAIRS	New	100.00	0.00
11	TO CHECK & REFIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
12	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS ,RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
Gross Labour Cost (\$\$)			6,250.00	1,470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >