

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22004442/BQY3Q2**Date:** 25/05/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00236642103

Claimant Vehicle No : SJE4997C **Insured Vehicle No :** SGZ9935Z

Date of Loss: 08/05/2022 Nature of Claim: TP Claim No: SNM22D203215/C02/TAYHP

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJE4997C**

Make & Model: SUZUKI SWIFT, 1.3 Engine No: HIDDEN

Reg. Date: (Man. Year: 1900) Chassis No: ZC71S419543

Colour: Black Odometer: 190658 km

Engine Capacity: 1242 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/55 R15 Rear Tyre Size: 195/55 R15

Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,802.02	757.64	7,044.38	90.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,300.00	860.00	4,440.00	83.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	13,102.02	1,617.64	11,484.38	87.65
Approved Total (Overridden) (\$\$)		1,300.00		
(\$\$)	13,102.02	1,300.00	11,802.02	90.08
+ GST 8.00/8.00% (\$\$)	1,048.16	104.00	944.16	90.08
Nett Amount (\$\$)	14,150.18	1,404.00	12,746.18	90.08

INSPECTION

Date of Assignment: 09/05/2023

Date Inspected: 12/05/2022 Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit)
8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 4.0 days

Adjuster: Lim Teow Guan**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 May 2023)
Parts:	144	SUZUKI SWIFT 1.3 (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJE4997C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Broken	569.65 FL	*569.65 FL
2	1		*REAR BUMPER SIDE RETAINER RH	Necessary	25.55 FL	*25.55 FL
3	1		*REAR BUMPER SIDE RETAINER LH	Necessary	25.55 FL	*25.55 FL
4	1		*REAR BUMPER SIDE BRACKET RH	Not Damaged	25.55 FL	*- FL
5	1		*REAR BUMPER SIDE BRACKET LH	Not Damaged	25.55 FL	*- FL
6	1		*REAR BUMPER BEAM	Not Damaged	71.10 FL	*- FL
7	1		*REAR TAILGATE	Not Damaged	628.10 FL	*- FL
8	1		*REAR TAILGATE LOCK	Not Damaged	160.00 FL	*- FL
9	1		*REAR TAILGATE LOCK STRIKER	Not Damaged	28.60 FL	*- FL
10	1		*REAR TAILGATE OUTER HANDLE	Not Damaged	55.60 FL	*- FL
11	1		*REAR TAILGATE INNER TRIM BOARD	Not Damaged	223.00 FL	*- FL
12	1		*REAR TAILGATE WEATHERSTRIP	Not Damaged	82.10 FL	*- FL
13	1		*REAR TAILGATE WINDSCREEN GLASS MOULDING	Not Damaged	105.10 FL	*- FL
14	1		*REAR TAILGATE EMBLEM	Not Damaged	42.50 FL	*- FL
15	1		*REAR TAILGATE SWIFT EMBLEM	Not Damaged	31.70 FL	*- FL
16	1		*REAR TAILLAMP ASSEMBLY RH	Not Damaged	452.00 FL	*- FL
17	1		*REAR TAILLAMP ASSEMBLY LH	Not Damaged	452.00 FL	*- FL
18	1		*REAR END PANEL	Not Damaged	336.00 FL	*- FL
19	1		*REAR END PANEL TOP GARNISH	Not Damaged	133.00 FL	*- FL
20	1		*REAR END PANEL AIR VENT	Not Damaged	62.80 FL	*- FL
21	1		*REAR SPARE TYRE PANEL TOP BOARD	Not Damaged	179.30 FL	*- FL
22	1		*REAR SPARE TYRE PANEL	Not Damaged	598.50 FL	*- FL
23	1		*REAR FENDER INNER SHIELD RH	Not Damaged	102.65 FL	*- FL
24	1		*REAR FENDER INNER TRIM RH	Not Damaged	592.00 FL	*- FL
25	1		*REAR FENDER RH	Repair	360.75 FL	*- FL
26	1		*REAR SHOCK ABSORBER RH	Not Damaged	215.00 FL	*- FL
27	1		*REAR WHEEL BEARING RH	Not Damaged	115.00 FL	*- FL
28	1		*REAR CROSSMEMBER ASSEMBLY	Not Damaged	732.85 FL	*- FL
29	1		*REAR EXHAUST MUFFLER	Not Damaged	280.05 FL	*- FL
30	2		*REAR EXHAUST MUFFLER MOUNTING	Not Damaged	32.00 FL	*- FL
31	1		*REAR NUMBER PLATE	Not Damaged	50.00 FS	*- FS
32	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
33	1		*SET REAR TAILLAMP CLIPS	Not Damaged	50.00 FS	*- FS
34	1		*SET REAR END PANEL TOP GARNISH CLIPS	Not Damaged	50.00 FS	*- FS
35	1		*SET REAR FENDER INNER SHIELD CLIPS	Not Damaged	40.00 FS	*- FS
36	1		*SET REAR FENDER INNER TRIM CLIPS	Not Damaged	80.00 FS	*- FS
37	1		*SET REAR TAILGATE INNER TRIM CLIPS	Not Damaged	50.00 FS	*- FS
38	1		*REAR TAILGATE WINDSCREEN GLASS SEALANT	Not Damaged	150.00 FS	*- FS
39	1		*REAR TAILGATE SEALANT	Not Damaged	150.00 FS	*- FS
40	1		*REAR END PANEL SEALANT	Not Damaged	150.00 FS	*- FS
41	1		*REAR SPARE TYRE PANEL SEALANT	Not Damaged	150.00 FS	*- FS
42	2		*REAR FENDER SEALANT	Not Damaged	300.00 FS	*- FS
43	1		*REAR REVERSE CAMERA	Not Damaged	550.00 FS	*- FS
44	1		*SET REAR BUMPER REVERSE SENSOR	Scratched	250.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 8,813.55 850.75

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 15.00/15.00% (S\$)					1,011.53	93.11
Total Parts (S\$)					7,802.02	757.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT ,REMOVE & REFIX PARTS	New	1,500.00	400.00
2	TO SPRAY PAINT AFFECTED AREAS	New	1,500.00	400.00
3	WIRING & BULB CHECK	New	100.00	0.00
4	TO REMOVE & REFIX REAR TAILGATE WINDSCREEN GLASS	New	150.00	0.00
5	TO TRANSFER REAR TAILGATE MECHANISM	New	150.00	0.00
6	TO REMOVE & REFIX REAR REVERSE CAMERA	New	150.00	0.00
7	TO REMOVE & REFIX REAR BUMPER REVERSE SENSOR	New	120.00	60.00
8	TO REMOVE & REFIX REAR EXHAUST PIPE	New	150.00	0.00
9	TO APPLY ANTI RUST ON AFFECTED PARTS	New	100.00	0.00
10	TO REMOVE & REFIX INTERIOR UPHOLSTERY TO FACILITATE REPAIRS	New	150.00	0.00
11	TO REMOVE & REFIX UNDERCARRIAGE	New	500.00	0.00
12	TO CONDUCT FOUR WHEEL ALIGNMENT	New	150.00	0.00
13	TO CONDUCT WATER LEAK TEST	New	100.00	0.00
14	TO SEND FOR DIAGNOSTIC AND RESET CONTROL UNIT PROGRAMMING & CALIBRATION	New	480.00	0.00
Gross Labour Cost (\$\$)			5,300.00	860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >