

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22004444/BPA3Q2**Date:** 18/05/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0100610938
Claimant Vehicle No :	SCP2799X	Insured Vehicle No :	SFS8090R
Date of Loss:	11/05/2022	Nature of Claim:	TP
		Claim No:	1378591031SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SCP2799X		
Make & Model:	TOYOTA PICNIC, 2.0 W/O ROOF RACK (A)	Engine No:	1AZ5428400
Reg. Date:	05/09/2006 (Man. Year: 2006)	Chassis No:	JTEGH23B000021961
Colour:	Silver	Odometer:	213231 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,337.70	3,065.65	6,272.05	67.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,900.00	1,660.00	2,240.00	57.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,237.70	4,725.65	8,512.05	64.30
Approved Total (Overridden) (S\$)		3,800.00		
(S\$)	13,237.70	3,800.00	9,437.70	71.29
+ GST 8.00/8.00% (S\$)	1,059.02	304.00	755.02	71.29
Nett Amount (S\$)	14,296.72	4,104.00	10,192.72	71.29
+ Car Rental (7.0 x S\$120.00/day) (S\$)		840.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,951.45		
Global Sum Settlement (S\$)		4,950.00		

INSPECTION

Date of Assignment:	12/05/2022	Team Autopro Pte Ltd (sin Ming) (HQ)
Date Inspected:	12/05/2022 Inspected At:	160 SIN MING DRIVE, #01-14 SIN MING AUTOCITY
Estimated Period of Repair:	8.0 days	Singapore 575722

Adjuster: Lim Teow Guan**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,375.90 FL	*1,267.00 FL
2	1		*TAILGATE LOGO	Necessary	143.20 FL	*70.00 FL
3	1		*TAILGATE EMBLEM TOYOTA	Necessary	108.60 FL	*75.00 FL
4	1		*TAILGATE EMBLEM PICNIC	Necessary	105.30 FL	*70.00 FL
5	1		*TAILGATE INNER TRIM BOARD	Not Damaged	498.20 FL	*- FL
6	1		*TAILGATE INNER LOCK	Jammed	404.80 FL	*246.00 FL
7	1		*TAILGATE WEATHERSTRIP	Torn	188.30 FL	*188.30 FL
8	1		*TAILGATE WINDSCREEN MOULDING	Necessary	187.90 FL	*187.90 FL
9	1		*REAR BUMPER	Broken	1,352.00 FL	*586.00 FL
10	2		*REAR BUMPER REFLECTOR	Broken	426.80 FL	*160.00 FL
11	2		*REAR BUMPER SUPPORT BRACKET	No such part	274.80 FL	*- FL
12	2		*REAR BUMPER TOW CAP	Not Damaged	372.40 FL	*- FL
13	1		*REAR END PANEL	Dented	812.50 FL	*584.00 FL
14	1		*REAR END PANEL TOP GARNISH	Not Damaged	321.00 FL	*- FL
15	1		*REAR FLOOR PANEL	Not Damaged	1,025.30 FL	*- FL
16	2		*REAR FLOOR PANEL TOP BOARD	Not Damaged	1,161.40 FL	*- FL
17	2		*REAR FLOOR PANEL TOP SIDE BOARD	Not Damaged	636.00 FL	*- FL
18	1		*REAR FLOOR PANEL TOP BOARD REAR GARNISH	Not Damaged	398.00 FL	*- FL
19	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
20	1		*TAILGATE SEALANT	Necessary	100.00 FS	*30.00 FS
21	1		*TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
22	1		*TAILGATE WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS
23	1		*TAILGATE WINDSCREEN INNER SEAL	Not Necessary	80.00 FS	*- FS
24	1		*TAILGATE WINDSCREEN PRIMER & CLEANER	Not Necessary	60.00 FS	*- FS
25	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
26	2		*REAR BUMPER SIDE RETAINER	Necessary	373.40 FS	*170.00 FS
27	1		*REAR BUMPER REVERSE SENSOR (3 PCS)	Necessary	600.00 FS	*200.00 FS
28	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*30.00 FS
29	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
30	1		*REAR FLOOR PANEL SEALANT	Not Necessary	100.00 FS	*- FS
31	1		*REAR FLOOR PANEL INSULATOR	Not Necessary	250.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	11,785.80	3,924.20
- List Item Discount on L Items 25.00/25.00% (\$)	2,448.10	858.55
Total Parts (\$)	9,337.70	3,065.65

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R TAILGATE COMPONENT	New	150.00	80.00
2	R&R TAILGATE WINDSCREEN	New	250.00	120.00
3	R&R REAR BUMPER REVERSE SENSOR	New	100.00	60.00
4	CHECK WIRING	New	100.00	0.00
5	UPHOLSTERY	New	300.00	0.00
6	PANEL BEATING	New	1,400.00	800.00
7	RUST PROOFING	New	200.00	0.00
8	SPRAY PAINTING	New	1,400.00	600.00
Gross Labour Cost (S\$)			3,900.00	1,660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >