

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22004446/APA3Q2**Date:** 30/12/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070165846
Claimant Vehicle No :	SNA1646J	Insured Vehicle No :	SMW5422H
Date of Loss:	02/05/2022	Nature of Claim:	TP
		Claim No:	4556230457SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNA1646J		
Make & Model:	VOLKSWAGEN GOLF, 1.4 TSI CL (A)	Engine No:	CZCC03911
Reg. Date:	15/10/2019 (Man. Year: 2019)	Chassis No:	WVWZZZAUZKW154009
Colour:	Red	Odometer:	23419 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,423.00	4,535.60	3,887.40	46.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,650.00	1,970.00	680.00	25.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,073.00	6,505.60	4,567.40	41.25
Approved Total (Overridden) (S\$)		5,200.00		
Nett Amount (S\$)	11,073.00	5,200.00	5,873.00	53.04
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
Nett Liability (S\$)		5,560.00		

INSPECTION

Date of Assignment:	04/05/2022	Advance Auto Garage (HQ)
Date Inspected:	04/05/2022 Inspected At:	23 KAKI BUKIT AVENUE 4 #04-01 AAS KAKI BUKIT CENTRE
Estimated Period of Repair:	5.0 days	Singapore 415933

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH DOOR	Dented	1,585.00 F	*1,585.00 FL
2	1		*FRONT RH DOOR LOCK	Not Necessary	496.00 F	*- FL
3	1		*FRONT RH DOOR WEATHERSTRIPE	Necessary	386.00 F	*386.00 FL
4	1		*FRONT RH DOOR GLASS REGULATOR GEAR	Damaged	365.00 F	*365.00 FL
5	1		*FRONT RH DOOR GLASS REGULATOR MOTOR	Not Necessary	395.00 F	*- FL
6	1		*FRONT RH DOOR INNER TRIM BOARD	Cracked	786.00 F	*786.00 FL
7	1		*FRONT RH DOOR INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*50.00 FS
8	1		*CENTRE PILLAR	Repair	989.00 F	*- FL
9	1		*REAR RH DOOR	Dented	1,480.00 F	*1,480.00 FL
10	1		*REAR RH DOOR LOCK	Not Necessary	459.00 F	*- FL
11	1		*REAR RH DOOR WEATHERSTRIPE	Necessary	382.00 F	*382.00 FL
12	1		*REAR RH WHEEL RIM	Not Necessary	800.00 FS	*- FS
13	1		*REAR RH TYRE	Not Necessary	250.00 FS	*- FS
					Sub Total (\$)	8,423.00 5,034.00
					- List Item Discount on L Items 0.00/10.00% (\$)	0.00 498.40
					Total Parts (\$)	8,423.00 4,535.60

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,000.00	800.00
2	SPRAY PAINTING	New	1,000.00	900.00
3	WIRING	New	50.00	30.00
4	TO TRANSFER FRONT DOOR FITTINGS	New	150.00	80.00
5	TO TRANSFER REAR DOOR FITTINGS	New	150.00	80.00
6	TO PERFORM WHEEL ALIGNMENT	New	150.00	0.00
7	TO SPRAY TUFF COAT	New	150.00	80.00
Gross Labour Cost (\$)			2,650.00	1,970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >