

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

OPINION ON REPAIR COST FOR VEHICLE NO. SNE 5045X

Qty	Description of Parts	Condition	Recommended (\$)
	REPLACEMENT OF PARTS		
1	RH/ REAR LAMP COMBINATION (SN)	BROKEN	578.81
1	REAR BUMPER LOWER TRIM (SN)	CUT	494.05
1	RH/ REAR BUMPER LATERAL SUPPORT (SN)	BROKEN	135.49
			1,208.35
	<u>LABOUR</u>		
	DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.		240.00
	RESPRAY REAR BUMPER.		800.00
	USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD.		240.00
	CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE.		120.00
			1,400.00
	GRAND TOTAL		2,608.35

RECOMMENDED COST OF REPAIRS	2,608.35
-----------------------------	----------

Report Ref No. CS1/SCD22004447/Eqy3e2

CHEN TSUE YEE

Automotive Assessor

P

ANG BRYAN TANI

Automotive Assessor / Investigator