Adjuster Report 10/26/22, 10:27 AM

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG22004448/KPA3Q2

26/10/2022 Date:

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070012775-02

Claimant Vehicle Insured Vehicle No: SJE8307T SLH9091T No:

Date of Loss: 11/05/2022 Nature of Claim: TP Claim No: 3489802038SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJE8307T**

Make & Model: MAZDA 2, 1.5 R (A) Engine No: ZY464286

Reg. Date: 09/05/2008 (Man. Year: 2008) Chassis No: JM0DE10Y180113800

Colour: Metallic Blue Odometer: 145053 km

Engine Capacity: 1498 cc Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes **Engine Modification:** No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/50Z R16 Rear Tyre Size: 205/50Z R16 Front Left Side: Rear Left Side: ROADMARCH 6 mm Michelin 2 mm Front Right Side: ROADMARCH 6 mm Rear Right Side: Michelin 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,436.60	2,950.20	486.40	14.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,760.00	1,250.00	510.00	28.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,196.60	4,200.20	996.40	19.17
Approved Total (Overridden) (S\$)		3,350.00		
(S\$)	5,196.60	3,350.00	1,846.60	35.53
+ GST 7.00/7.00% (S\$)	363.76	234.50	129.26	35.53
Nett Amount (S\$)	5,560.36	3,584.50	1,975.86	35.53
+ Loss of Use (4.0 x S\$60.00/day) (S\$) + Doc/Search Fee (S\$)		240.00		
		2.00		
Ne	ett Liability (S\$)	3,826.50		

INSPECTION

Date of Assignment: 30/05/2022

Cheng Hoe Motor Pte Ltd (Yishun)

Blk 1019 #01-374/382, Yishun Industrial Park A Date Inspected: 30/05/2022 Inspected At:

Singapore 768761

Estimated Period of Repair: 4.0 days

KENNETH KONG CHEW HSIAO TONG Adjuster: Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

4				
1	*REAR BUMPER	Buckled	875.00 FL	*875.00 FL
1	*REAR BUMPER REINFORCEMENT	Buckled	486.00 FL	*486.00 FL
6	*REAR BUMPER CLIPS	Necessary	27.00 FL	*27.00 FL
1	*TAILLAMP LH	Cut	395.00 FL	*395.00 FL
1	*REAR TAILGATE	Bent	896.00 FL	*896.00 FL
1	*TAILGATE LOGO	Necessary	47.00 FL	*47.00 FL
1	*TAILGATE EMBLEM MAZDA	Necessary	35.00 FL	*35.00 FL
1	*TAILGATE INNER LOCK	Dented	125.00 FL	*125.00 FL
1	*TAILGATE INNER RUBBER	Serviceable	108.00 FL	*- FL
1	*REAR WINDSCREEN GLASS MOULDING	Necessary	105.00 FL	*105.00 FL
1	*REAR PANEL	Repair	398.00 FL	*- FL
1	*REAR PANEL TOP INNER GARNISH	Serviceable	102.00 FL	*- FL
1	*REAR WINDSCREEN GLASS SEALANT	Necessary	40.00 FS	*40.00 FS
1	*REAR NUMBER PLATE	Cracked	35.00 FS	*35.00 FS
1	*SET REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
1	*SET REAR NUMBER PLATE LAMP	Mtg Cracked	353.00 FL	*353.00 FL
nchise part. S=SpcNe	ett. L=ListItemDisc.	_		
		Sub Total (S\$)	4,227.00	3,619.00
- List Item Discount on L Items 20.00/20.00% (S\$)				668.80
		Total Parts (S\$)	3,436.60	2,950.20
		*REAR BUMPER CLIPS *TAILLAMP LH *REAR TAILGATE *TAILGATE LOGO *TAILGATE EMBLEM MAZDA *TAILGATE INNER LOCK *TAILGATE INNER RUBBER *REAR WINDSCREEN GLASS MOULDING *REAR PANEL *REAR PANEL TOP INNER GARNISH *REAR WINDSCREEN GLASS SEALANT *REAR WINDSCREEN GLASS SEALANT *REAR NUMBER PLATE *SET REVERSE SENSOR *SET REAR NUMBER PLATE LAMP chise part. S=SpcNett. L=ListItemDisc.	**REAR BUMPER CLIPS *TAILLAMP LH Cut *REAR TAILGATE Bent *TAILGATE LOGO Necessary *TAILGATE EMBLEM MAZDA Necessary *TAILGATE INNER LOCK Dented *TAILGATE INNER RUBBER *TAILGATE INNER RUBBER *REAR WINDSCREEN GLASS MOULDING Necessary *REAR PANEL *REAR PANEL *REAR PANEL TOP INNER GARNISH Serviceable *REAR WINDSCREEN GLASS SEALANT Necessary *REAR WINDSCREEN GLASS SEALANT Necessary *REAR NUMBER PLATE Cracked *SET REVERSE SENSOR Shorted *SET REVERSE SENSOR Shorted *SET REAR NUMBER PLATE LAMP Mtg Cracked Chise part. S=SpcNett. L=ListItemDisc.	**REAR BUMPER CLIPS

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	REMOVE AND REFIT REAR WINDSCREEN GLASS	New	100.00	100.00
2	REMOVE AND REFIT REAR BUMPER ASSY ,TAILLAMPS ,T ,REAR SPOILER ,REAR WIPER ,REAR LOCK ASSY.TO CUT RENEW REAR END PANEL AND REALIGN THE SAME		800.00	520.00
3	PUTTY AND RESPRAY ON REAR PANEL ,REAR BUMPER ,REINFORCEMENT ,TAILGATE AND REAR AFFECTED	New	800.00	600.00
4	RUSTPROOFING	New	60.00	30.00
		Gross Labour Cost (S\$)	1,760.00	1,250.00
	Report was unsubmitte	ed during this print-out.		

< END OF ESTIMATES >