

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22004449/APA3Q2**Date:** 11/04/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070084087-01
Claimant Vehicle No :	SMA3299B	Insured Vehicle No :	GBG620A
Date of Loss:	11/05/2022	Nature of Claim:	TP
		Claim No:	6918012811SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMA3299B		
Make & Model:	AUDI Q3, 1.4 TFSI (A)	Engine No:	CZDC39741
Reg. Date:	31/05/2021 (Man. Year: 2021)	Chassis No:	WAUZZZF31M1115996
Colour:	Black	Odometer:	13772 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/65 R17	Rear Tyre Size:	215/65 R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	40,361.40	12,035.36	28,326.04	70.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	15,392.00	8,842.00	6,550.00	42.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	55,753.40	20,877.36	34,876.04	62.55
+ GST 8.00/8.00% (S\$)	4,460.27	1,670.19	2,790.08	62.55
Nett Amount (S\$)	60,213.67	22,547.55	37,666.12	62.55
+ Loss of Use (12.0 x S\$60.00/day) (S\$)		720.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		23,269.55		

INSPECTION

Date of Assignment:	19/05/2022		
Date Inspected:	19/05/2022	Inspected At:	Premium Automobiles Pte Ltd (HQ) 55 UBI ROAD 1 Singapore 408699
Estimated Period of Repair:	10.0 days		

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	2,308.00 FS	*- FS
2	2		*FRONT BUMPER CLOSING ELEMENT -LH/RH	Not Necessary	132.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE -CENTER	Not Necessary	242.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE LOWER COVER	Not Necessary	58.00 FS	*- FS
5	2		*FRONT BUMPER GRILLE -LH/RH	Not Necessary	248.00 FS	*- FS
6	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	212.00 FS	*- FS
7	1		*FRONT BUMPER SPOILER	Not Necessary	426.00 FS	*- FS
8	1		*FRONT BUMPER BRACKET	Not Necessary	24.00 FS	*- FS
9	1		*FRONT BUMPER AIR GUIDE GRILLE -LH/RH	O/S Cut	342.00 FS	*136.40 FS
10	1		*RADIATOR GRILLE	Cracked	1,594.00 FS	*1,275.20 FS
11	1		*RADIATOR GRILLE STICKER PLATE	Cracked	271.00 FS	*216.80 FS
12	1		*RADIATOR GRILLE COVER CAP	Not Necessary	47.00 FS	*- FS
13	1		*RADIATOR GRILLE BRACKET	Not Necessary	46.00 FS	*- FS
14	1		*RADIATOR GRILLE SECURING STRIP	Not Necessary	37.00 FS	*- FS
15	1		*FRONT CAMERA	Not Necessary	1,261.00 FS	*- FS
16	1		*FRONT BUMPER REINFORCEMENT BEAM	Dented	974.00 FS	*778.80 FS
17	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	114.00 FS	*- FS
18	2		*FRONT BUMPER GUIDE SECTION -LH/RH	Not Necessary	86.00 FS	*- FS
19	1		*FRONT BUMPER TOP COVER	Not Necessary	137.00 FS	*- FS
20	1		*CAUTION STICKER	Not Necessary	16.00 FS	*- FS
21	1		*AIR COND STICKER	Not Necessary	9.00 FS	*- FS
22	2		*FRONT PARKING AID SENSOR	Not Necessary	530.00 FS	*- FS
23	4		*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	10.00 FS	*- FS
24	2		*HEADLIGHT MOUNTING -LH/RH	Cracked	264.00 FS	*210.40 FS
25	2		*HEADLIGHT -LH/RH	Not Necessary	11,904.00 FS	*- FS
26	2		*LIFT CYLINDER -LH/RH	Not Necessary	462.00 FS	*- FS
27	1		*LIFT CYLINDER HOSE	Not Necessary	92.00 FS	*- FS
28	1		*RADIATOR AIR GUIDE OUTER -LH/RH	O/S Torn	86.00 FS	*34.08 FS
29	2		*RADIATOR AIR GUIDE -UPPER /LOWER	Not Necessary	96.00 FS	*- FS
30	2		*FRONT WHEELARCH COVER -LH/RH	Necessary	566.00 FS	*452.00 FS
31	1		*REAR BUMPER	Deformed	1,738.00 FS	*1,390.40 FS
32	1		*REAR BUMPER FIXING PARTS	Not Necessary	220.00 FS	*- FS
33	1		*REAR BUMPER SPOILER	Deformed	510.00 FS	*408.00 FS
34	1		*REAR BUMPER TOWING EYE	Not Necessary	48.00 FS	*- FS
35	1		*REAR BUMPER BRACKET	Damaged	53.00 FS	*42.40 FS
36	2		*REAR LIGHT REFLECTOR -LH/RH	Not Necessary	92.00 FS	*- FS
37	2		*TAIL LIGHT INNER -LH/RH	Not Necessary	2,060.00 FS	*- FS
38	2		*TAIL LIGHT TRIM INNER -LH/RH	Not Necessary	68.00 FS	*- FS
39	1		*REAR BUMPER REINFORCEMENT BEAM	Dented	693.00 FS	*554.40 FS
40	1		*REAR BUMPER HOLDING STRAP -CENTER	Not Necessary	120.00 FS	*- FS
41	2		*REAR BUMPER GUIDE SECTION -LH/RH	Not Necessary	142.00 FS	*- FS
42	2		*REAR PARKING AID SENSOR	Not Necessary	530.00 FS	*- FS
43	4		*REAR PARKING AID SENSOR SEAL RING	Not Necessary	10.00 FS	*- FS
44	1		*REAR LID	Dented	3,767.00 FS	*3,013.60 FS
45	1		*REAR PACKING ADHESIVE	Necessary	21.00 FS	*16.72 FS
46	1		*REAR LID ATTACHMENT PARTS	Not Necessary	393.00 FS	*- FS
47	1		*REAR LID LOCK	Not Necessary	292.00 FS	*- FS
48	1		*REAR LID LOCK COVER	Not Necessary	8.00 FS	*- FS
49	1		*REAR LID STRIKER PLATE	Not Necessary	74.00 FS	*- FS
50	1		*REAR LID LOCK ACTUATOR	Not Necessary	1,478.00 FS	*- FS
51	1		*REAR LID FLAP GASKET	Necessary	229.00 FS	*182.80 FS
52	1		*AUDI EMBLEM	Necessary	144.00 FS	*114.80 FS
53	1		*Q3 EMBLEM	Necessary	104.00 FS	*82.80 FS
54	1		*REAR WINDSCREEN	Necessary	1,064.00 FS	*851.20 FS
55	1		*PRIMER	Necessary	22.00 FS	*17.36 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	2		*REAR LID TOP SPOILER -LH/RH	Necessary	470.00 FS	*375.20 FS
57	2		*REAR LID GASKET CLIP	Not Necessary	16.00 FS	*- FS
58	1		*REAR END PANEL TRIM	Not Necessary	213.00 FS	*- FS
59	2		*REAR WHEEL ARCH COVER -LH/RH	Necessary	566.00 FS	*452.00 FS
60	2		*LED LICENCE PLATE	Not Necessary	113.00 FS	*- FS
61	1		*REAR LID TRIM PANEL -LOWER	Not Necessary	541.00 FS	*- FS
62	1		*REAR WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
63	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
64	1		*REAR NO PLATE	Not Necessary	60.00 FS	*- FS
65	1		*SUNDRIES	Necessary	500.00 FS	*21.60 FS
66	1		*REAR CROSS PANEL	Dented	262.80 FS	*262.80 FS
67	4		*REAR LID BUNGS	Necessary	105.60 FS	*105.60 FS
68	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
69	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
70	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
71	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	40,361.40	12,035.36
--------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS HORNS ,OUTSIDE TEMPERATURE SENSOR ,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	800.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER AND BOTH HEADLIGHT ,RE-ORGANIZE CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	1,200.00	500.00
4	TO RESPRAY FRONT BUMPER	New	1,000.00	550.00
5	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR	New	360.00	360.00
6	TO REMOVE AND TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM WIRE HARNESS FOR TAIL LIGHTS AND REAR WIPER ASSY	New	480.00	480.00
7	TO RENEW REAR WINDSCREEN TO FACILITATE RENEWAL OF REAR LID	New	480.00	480.00
8	TO CARRY OUT WATER SEEPAGE FOR REAR WINDSCREEN	New	200.00	150.00
9	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN	New	400.00	400.00
10	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID.TO REPAIR REAR END PANELLING .RE-ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	2,800.00	1,000.00
11	TO RESPRAY REAR BUMPER,REAR LID AND REAR END PANELLING	New	3,000.00	1,650.00
12	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
13	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS BATTERY MANAGER,FUSE AND RELAY TRAYS ELECTRICAL AND AUDIO EQUIPMENT INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY	New	1,600.00	1,600.00
14	TO CUT OUT AND WELD REAR END PANELLING	New	2,400.00	1,000.00
Gross Labour Cost (\$\$)			15,392.00	8,842.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >