

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22004451/AEA3Q2**Date:** 21/09/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700081245
Claimant Vehicle No :	SJM3002M	Insured Vehicle No :	SLU5586R
Date of Loss:	04/05/2022	Nature of Claim:	TP
		Claim No:	0603133423SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJM3002M	Engine No:	HR15045665B
Make & Model:	NISSAN LATIO, 1.5 AT ABS D/AIRBAG 2WD 4DR (A)	Chassis No:	JN1BAAC11Z0020541
Reg. Date:	13/11/2008 (Man. Year: 2008)	Odometer:	194826 km
Colour:	Red		
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,633.30	4,406.46	10,226.84	69.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,730.00	2,730.00	2,000.00	42.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,363.30	7,136.46	12,226.84	63.14
Approved Total (Overridden) (S\$)		5,700.00		
(S\$)	19,363.30	5,700.00	13,663.30	70.56
+ GST 7.00/7.00% (S\$)	1,355.43	399.00	956.43	70.56
Nett Amount (S\$)	20,718.73	6,099.00	14,619.73	70.56
+ Loss of Use (8.0 x S\$60.00/day) (S\$)		480.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		6,581.00		

INSPECTION

Date of Assignment:	05/05/2022		
Date Inspected:	05/05/2022	Inspected At:	SM Automotive (HQ) 756 JURONG WEST STREET 74, #12-60 Singapore 640756
Estimated Period of Repair:	7.0 days		

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Dented	995.20 F	*764.00 FL
2	1		*REAR BOOTLID HINGE	Not Necessary	91.10 F	*- FL
3	1		*REAR BOOTLID LOCK	Damaged	357.60 F	*198.00 FL
4	1		*REAR BOOTLID LOCK DETECTOR	Cracked	289.20 F	*92.00 FL
5	1		*REAR BOOTLID EMBLEM LOGO	Necessary	65.50 F	*65.50 FL
6	1		*REAR BOOTLID EMBLEM LATIO	Necessary	62.30 F	*62.30 FL
7	1		*REAR BOOTLID INNER TRIM	Not Necessary	246.10 F	*- FL
8	1		*REAR BOOTLID OUTER CHROME MOULDING	Not Necessary	329.50 F	*- FL
9	1		*REAR WEATHERSTRIPE	Cut	174.90 F	*174.90 FL
10	1		*REAR BUMPER	Distorted	694.50 F	*456.00 FL
11	1		*REAR BUMPER SPONGE	Cracked	131.10 F	*36.00 FL
12	2		*REAR BUMPER SIDE RETAINER	Necessary	158.40 F	*70.00 FL
13	2		*REAR BUMPER BRACKET	Dented	193.60 F	*193.60 FL
14	1		*REAR BUMPER BEAM	Not Necessary	259.80 F	*- FL
15	1		*REAR END PANEL	Dented	585.60 F	*585.60 FL
16	1		*REAR END PANEL TOP GARNISH	Cracked	298.10 F	*298.10 FL
17	1		*REAR END PANEL KEYLESS SENSOR	Cracked	163.40 F	*163.40 FL
18	1		*REAR SPARE TYRE COMPARTMENT PANEL	Repair	1,359.40 F	*- FL
19	1		*REAR SPARE TYRE TOP BOARD	Deformed	495.00 F	*495.00 FL
20	1		*REAR SPARE TYRE LOCK NUT	Not Necessary	38.50 F	*- FL
21	2		*REAR TAILLAMP	Cracked	996.20 F	*580.00 FL
22	2		*REAR TAILLAMP INNER PANEL	Repair	700.80 F	*- FL
23	2		*REAR TAILLAMP LOWER BRACKET	Not Necessary	72.80 F	*- FL
24	2		*REAR FENDER	Repair	1,903.20 F	*- FL
25	2		*REAR FENDER INNER COWLING	Not Necessary	252.80 F	*- FL
26	2		*REAR FENDER AIR VENT	Not Necessary	295.20 F	*- FL
27	1		*REAR FENDER INNER TRIM	N/S Crumpled	1,152.80 F	*295.00 FL
28	1		*REAR WINDSCREEN GLASS MOULDING	Not Necessary	145.30 F	*- FL
29	1		*REAR EXHAUST MUFFLER	Not Necessary	798.20 F	*- FL
30	2		*REAR EXHAUST MUFFLER RUBBER MOUNTING	Not Necessary	57.20 F	*- FL
31	1		*REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
32	1		*REAR REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
33	1		*REAR END PANEL SEALANT	Necessary	120.00 FS	*60.00 FS
34	1		*REAR WINDSCREEN GLASS SEALANT	Not Necessary	150.00 FS	*- FS
35	2		*REAR FENDER INNER TRIM CLIPS	Necessary	120.00 FS	*30.00 FS
36	2		*REAR FENDER INNER COWLING CLIPS	Not Necessary	120.00 FS	*- FS
37	1		*REAR BOOTLID INNER TRIM BOARD CLIPS	Not Necessary	40.00 FS	*- FS
38	1		*REAR NUMBER PLATE WITH CASING	Not Necessary	60.00 FS	*- FS
39	2		*REAR TAILLAMP CLIPS	Necessary	30.00 FS	*10.00 FS
40	1		*REAR TAILLAMP INNER PANEL SEALANT	Not Necessary	120.00 FS	*- FS
41	1		*REAR SPARE TYRE COMPARTMENT PANEL SEALANT	Not Necessary	150.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	14,633.30	4,859.40
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	452.94
Total Parts (\$)	14,633.30	4,406.46

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING	New	1,600.00	1,100.00
2	LABOUR FOR SPRAYPAINTING	New	1,600.00	1,400.00
3	LABOUR FOR REMOVE & REFIX REAR WINDSCREEN GLASS	New	150.00	0.00
4	LABOUR FOR REMOVE & RENEW REAR EXHAUST MUFFLER /REPAIR EXHAUST	New	300.00	0.00
5	LABOUR FOR REMOVE & REFIX REAR UPHOLSTERY /CARPET TRIM BOARD	New	200.00	80.00
6	LABOUR FOR REPAIR & STRAIGHTEN BOTH REAR CHASSIS FRAME	New	500.00	0.00
7	WIRING CHECK	New	80.00	30.00
8	TO APPLY RUST PROOF /TUFF COAT ON ACCIDENT AREAS	New	300.00	120.00
			Gross Labour Cost (\$)	4,730.00
				2,730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >