

SMD 5654E.

TP AXA

Hyundai I30

Dense.

KMHDESIDMAU250128

Rear RH Door	Dented	1173.70 ✓
Rear RH Door Lock	Damaged	246.50 ✓
Rear RH Door Weatherstripe	MP MR	178.40 X
Rear RH Door Outer Handle (Carbon Fibre)	MR	280(SN) 180(SN)
Rear RH Door Inner Trim Board	MP MR	632.20 X
Rear RH Door Inner Trim Board Clip	MP MR	30(SN) X
Rear RH Door Glass Regulator Grease	MP MR	288.20 X
Rear RH Door Black Tape	MR	60(SN) ✓
Rear RH Door Visor	MR	100(SN) 60(SN)
Rear RH Fender	Distorted	1605.10 ✓
Rear RH Fender Glass Moulding	MR	84.20 ✓
Rear RH Fender Glass Sealant	MR	40(SN) ✓

SMD5654E.

Rear RH Wheel Rim. ~~HP~~ 580(SN) +

Front RH Wing Mirror. Rep's 587.50. +

3109.50 S.N: 340

2487.60

Panel Beating
Spray Painting

Wiring

To remove upholstery.

To remove rear fender glass

To transfer door fittings.

To perform wheel alignment.

1430

~~1000~~ 600

~~800~~ 600.

~~50~~ 30

~~150~~ 60.

~~120~~ 60

~~150~~ 80

~~150~~ X

total: 4257.60

L/S: 3.4K.

04 Days.

8405.8

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: