

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22004460/RNCE2**Date:** 28/10/2022**REFERENCE**

Insured/Claimant:	CHEONG KWAN CHOONG	Policy No:	2100327724	
Date of Loss:	24/04/2022	Nature of Claim:	OD	Claim No: 5934037534SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKJ3303Z	Engine No:	CHV017209
Make & Model:	AUDI A7 SPORTBACK, 2.8 FSI QUATTRO (A)	Chassis No:	WAUZZZ4G3DN080795
Reg. Date:	16/01/2013 (Man. Year: 2012)	Odometer:	83920 km
Colour:	White		
Engine Capacity:	2773 cc		
Market Value/New Car Price:	S\$48,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/40Z R19	Rear Tyre Size:	255/40Z R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,967.00	3,908.48	11,058.52	73.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,672.00	1,722.00	2,950.00	63.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,639.00	5,630.48	14,008.52	71.33
- Excess (S\$)	3,500.00	3,500.00	0.00	0.00
(S\$)	16,139.00	2,130.48	14,008.52	86.80
+ GST 7.00/7.00% (S\$)	1,129.73	149.13	980.60	86.80
Nett Amount (S\$)	17,268.73	2,279.61	14,989.12	86.80

INSPECTION

Date of Assignment:	12/05/2022		
Date Inspected:	11/05/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

Adjuster: MOHD RASUL**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Deformed	3,591.00 FS	*2,872.80 FS
2	1	*FRONT BUMPER CLOSING ELEMENT - CENTER	Not Necessary	248.00 FS	*- FS
3	2	*FRONT BUMPER CLOSING ELEMENT - LH / RH	Not Necessary	230.00 FS	*- FS
4	1	*FRONT BUMPER FIXING PARTS	Not Necessary	287.00 FS	*- FS
5	1	*FRONT BUMPER AIR GUIDE GRILLE	Not Necessary	171.00 FS	*- FS
6	1	*FRONT BUMPER CLOSING ELEMENT - LOWER	Cracked	237.00 FS	*189.20 FS
7	1	*FRONT BUMPER SPOILER	Not Necessary	276.00 FS	*- FS
8	1	*RADIATOR GRILLE	Not Necessary	1,578.00 FS	*- FS
9	1	*QUATTRO EMBLEM	Not Necessary	111.00 FS	*- FS
10	1	*RADIATOR GRILLE COVER	Not Necessary	31.00 FS	*- FS
11	1	*LICENCE PLATE HOLDER	Not Necessary	479.00 FS	*- FS
12	1	*FRONT BUMPER GRILLE - LH	Missing	283.00 FS	*226.40 FS
13	1	*FRONT BUMPER END CAP - LH	Missing	65.00 FS	*51.92 FS
14	1	*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	111.00 FS	*- FS
15	1	*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	927.00 FS	*- FS
16	1	*FRONT BUMPER TOP COVER	Not Necessary	137.00 FS	*- FS
17	1	*FRONT BUMPER GUIDE PIECE - LH	Not Necessary	50.00 FS	*- FS
18	1	*FRONT BUMPER BRACE - LH	Not Necessary	34.00 FS	*- FS
19	2	*FRONT BUMPER SUPPORT - LH	Not Necessary	29.00 FS	*- FS
20	4	*SET FRONT BUMPER POP RIVET	Not Necessary	7.00 FS	*- FS
21	1	*AIR COND STICKER	Not Necessary	34.00 FS	*- FS
22	1	*HORN - LH	Not Necessary	197.00 FS	*- FS
23	1	*HORN SUPPORT - LH	Not Necessary	53.00 FS	*- FS
24	1	*FRONT PARKING AID SENSOR (NPA)	Not Necessary	0.00 FS	*- FS
25	4	*FRONT PARKING AID SENSOR SEAL RING - INNER / OUTER	Not Necessary	6.00 FS	*- FS
26	1	*FRONT WHEEL HOUSING LINER - LH	Not Necessary	299.00 FS	*- FS
27	1	*FRONT WHEEL SPOILER - LH	Cracked	414.00 FS	*331.20 FS
28	1	*HEADLIGHT MOUNTING - LH	Not Necessary	132.00 FS	*- FS
29	1	*HEADLIGHT - LH	Serviceable	3,769.00 FS	*- FS
30	1	*HEADLIGHT MOUNTING UPPER - LH	Not Necessary	131.00 FS	*- FS
31	1	*LIFT CYLINDER	Cracked	259.00 FS	*207.20 FS
32	5	*LIFT CYLINDER HOSE	Not Necessary	215.00 FS	*- FS
33	1	*FRONT FENDER STONE GUARD FILM - LH	Not Necessary	128.00 FS	*- FS
34	1	*FRONT NO PLATE	Not Necessary	60.00 FS	*- FS
35	1	*SUNDRIES	Not Necessary	350.00 FS	*- FS
36	1	*WASHER HOSE ELBOW FITTING (Supplementary)	Damaged	33.00 F	*26.08 F
37	1	*WASHER HOSE CLAMP (Supplementary)	Necessary	5.00 F	*3.68 F

F=Franchise part. S=SpcNett.

Total Parts (S\$) 14,967.00 3,908.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHT. TO REPAIR LHS FRONT FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,600.00	500.00
4	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER	New	2,000.00	550.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			4,672.00	1,722.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >