

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22004461/APA3Q2**Date:** 08/12/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100498354
Claimant Vehicle No :	SML5081R	Insured Vehicle No :	SLK8012M
Date of Loss:	08/05/2022	Nature of Claim:	TP
		Claim No:	2019917613SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SML5081R		
Make & Model:	NISSAN QASHQAI, 2.0 CVT ABS D/AIRBAG 2WD 5DR S/R (A)	Engine No:	MR20382261W
Reg. Date:	23/11/2015 (Man. Year: 2015)	Chassis No:	SJNFBAJ11U1518741
Colour:	Bronze	Odometer:	92726 km
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R19	Rear Tyre Size:	225/45 R19
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	31,418.09	15,581.81	15,836.28	50.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,880.00	3,280.00	2,600.00	44.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	37,298.09	18,861.81	18,436.28	49.43
Approved Total (Overridden) (\$\$)		15,000.00		
(\$\$)	37,298.09	15,000.00	22,298.09	59.78
+ GST 7.00/7.00% (\$\$)	2,610.87	1,050.00	1,560.87	59.78
Nett Amount (\$\$)	39,908.96	16,050.00	23,858.96	59.78
+ Car Rental (10.0 x \$S\$100.00/day) (\$\$)		1,000.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		17,052.00		

INSPECTION

Date of Assignment:	10/05/2022	
Date Inspected:	10/05/2022	Inspected At: SM Automotive (HQ) 756 JURONG WEST STREET 74, #12-60 Singapore 640756
Estimated Period of Repair:	8.0 days	

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	964.10 FL	*781.00 FL
2	1		*REAR BUMPER REINFORCEMENT	Dented	795.20 FL	*674.00 FL
3	2		*REAR BUMPER BRACKET	Not Necessary	172.80 FL	*- FL
4	2		*REAR BUMPER SIDE RETAINER	Necessary	102.40 FL	*102.40 FL
5	1		*REAR BUMPER TOW COVER	Not Necessary	28.10 FL	*- FL
6	1		*REAR BUMPER SPONGE	Cracked	178.90 FL	*178.90 FL
7	2		*REAR BUMPER REFLECTOR	Cracked	133.20 FL	*133.20 FL
8	1		*REAR END PANEL	Dented	554.90 FL	*554.90 FL
9	1		*REAR END PANEL TOP GARNISH	Deformed	97.80 FL	*97.80 FL
10	1		*REAR SPARE TYRE COMPARTMENT PANEL	Not Necessary	916.50 FL	*- FL
11	1		*REAR SPARE TYRE BOARD	Not Necessary	138.60 FL	*- FL
12	1		*REAR WEATHERSTRIPE	Not Necessary	182.50 FL	*- FL
13	2		*REAR TAILLAMP	Not Necessary	797.00 FL	*- FL
14	2		*REAR TAILLAMP LOWER BRACKET	Not Necessary	69.20 FL	*- FL
15	1		*REAR TAILGATE	Repair	3,230.50 FL	*- FL
16	1		*REAR TAILGATE LOCK	Not Necessary	178.20 FL	*- FL
17	1		*REAR TAILGATE INNER TRIM BOARD	Not Necessary	363.90 FL	*- FL
18	2		*REAR TAILGATE LAMP	Not Necessary	704.40 FL	*- FL
19	1		*REAR TAILGATE OUTER GARNISH	Not Necessary	386.50 FL	*- FL
20	1		*REAR TAILGATE LOGO	Not Necessary	79.90 FL	*- FL
21	1		*REAR TAILGATE EMBLEM QASHQAI	Necessary	115.20 FL	*115.20 FL
22	1		*REAR TAILGATE EMBLEM XTRONIC	Necessary	51.50 FL	*51.50 FL
23	1		*REAR TAILGATE WINDSCREEN GLASS MOULDING	Not Necessary	177.90 FL	*- FL
24	1		*REAR EXHAUST MUFFLER	Dented	1,101.30 FL	*1,101.30 FL
25	2		*REAR EXHAUST MUFFLER RUBBER MOUNTING	Not Necessary	76.80 FL	*- FL
26	1		*FRONT BUMPER	Deformed	864.90 FL	*682.00 FL
27	1		*FRONT BUMPER REINFORCEMENT	Dented	956.10 FL	*665.00 FL
28	2		*FRONT BUMPER BRACKET	Not Necessary	45.40 FL	*- FL
29	1		*FRONT BUMPER SPONGE	Cracked	277.10 FL	*277.10 FL
30	2		*FRONT BUMPER SIDE RETAINER	Necessary	82.80 FL	*82.80 FL
31	2		*FRONT BUMPER FOG LAMP	Not Necessary	647.40 FL	*- FL
32	2		*FRONT BUMPER FOG LAMP OUTER CHROME	Not Necessary	260.20 FL	*- FL
33	1		*FRONT BUMPER TOW COVER	Deformed	28.10 FL	*28.10 FL
34	1		*FRONT GRILLE WITH CHROME	Cracked	603.80 FL	*603.80 FL
35	1		*FRONT GRILLE LOGO	Necessary	79.90 FL	*79.90 FL
36	2		*FRONT HEADLAMP	Cracked	4,285.80 FL	*4,285.80 FL
37	2		*FRONT HEADLAMP LOWER BRACKET	Not Necessary	88.20 FL	*- FL
38	1		*FRONT SUPPORT PANEL	Repair	676.30 FL	*- FL
39	1		*FRONT SUPPORT PANEL TOP GARNISH	Cracked	286.10 FL	*286.10 FL
40	1		*FRONT SUPPORT PANEL SENSOR	Not Necessary	632.50 FL	*- FL
41	1		*FRONT FENDER	O/S Buckled	1,733.00 FL	*866.50 FL
42	2		*FRONT FENDER OUTER GARNISH	Not Necessary	1,308.80 FL	*- FL
43	1		*WIPER TANK	Not Necessary	216.80 FL	*- FL
44	1		*AIR CON CONDENSER	Dented	766.30 FL	*766.30 FL
45	1		*RADIATOR	Dented	787.80 FL	*787.80 FL
46	1		*RADIATOR FAN /MOTOR /COWLING	Not Necessary	698.70 FL	*- FL
47	1		*INTER COOLER	Dented	2,121.60 FL	*680.00 FL
48	1		*BONNET	Dented	1,284.10 FL	*1,054.00 FL
49	2		*BONNET HINGE	Not Necessary	131.60 FL	*- FL
50	1		*BONNET FRONTAL RUBBER	Cut	65.20 FL	*65.20 FL
51	1		*BONNET LOCK	Not Necessary	57.50 FL	*- FL
52	1		*REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
53	2		*REAR TAILLAMP CLIPS	Not Necessary	40.00 FS	*- FS
54	1		*REAR TAILGATE WINDSCREEN GLASS SEALANT	Not Necessary	150.00 FS	*- FS
55	1		*REAR TAILGATE INNER TRIM CLIPS	Not Necessary	60.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	4		*REAR BUMPER REVERSE SENSOR	Damaged	480.00 FS	*350.00 FS
57	1		*REAR END PANEL SEALANT	Necessary	120.00 FS	*60.00 FS
58	2		*REAR FENDER INNER TRIM CLIPS	Not Necessary	60.00 FS	*- FS
59	1		*REAR NUMBER PLATE WITH CASING	Cracked	60.00 FS	*30.00 FS
60	1		*FRONT NUMBER PLATE WITH CASING	Deformed	60.00 FS	*30.00 FS
61	1		*FRONT BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
62	2		*FRONT BUMPER PARKED SENSOR	Damaged	280.00 FS	*200.00 FS
63	1		*AIR CON GAS	Necessary	120.00 FS	*40.00 FS
64	1		*RADIATOR COOLANT	Necessary	150.00 FS	*40.00 FS
65	2		*FRONT FENDER OUTER GARNISH CLIPS	Not Necessary	80.00 FS	*- FS
66	1		*STEREO SET WITH CASING	Damaged	780.00 FS	*380.00 FS
67	4		*REVERSE SENSOR	Damaged (3 PCS ONLY)	960.00 FL	*720.00 FL
68	1		*RADIATOR TOP GARNISH	Cracked	124.50 FL	*124.50 FL
69	1		*RADIATOR SIDE GUARD GARNISH	Deformed	35.90 FL	*35.90 FL
70	1		*HORN	Cracked	85.00 FL	*85.00 FL
71	1		*REAR KEYLESS SENSOR	Not Necessary	64.40 FL	*- FL
72	1		*EXHAUST SHIELD	Not Necessary	142.10 FL	*- FL
73	1		*FRONT TEMPERATURE SENSOR SWITCH	Damaged	24.90 FL	*24.90 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	34,620.10	17,180.90
- List Item Discount on L Items 10.00/10.00% (\$\$)	3,202.01	1,599.09
Total Parts (\$\$)	31,418.09	15,581.81

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE REVERSE SENSOR	New	100.00	60.00
2	TO REMOVE EXHAUST PIPE	New	150.00	80.00
3	LABOUR FOR PANEL BEATING	New	2,200.00	1,400.00
4	LABOUR FOR SPRAYPAINTING	New	1,600.00	1,400.00
5	LABOUR FOR REMOVE & TRANSFER REAR WINDSCREEN GLASS	New	150.00	0.00
6	LABOUR FOR REPAIR & STRAIGHTEN BOTH REAR CHASSIS FRAME	New	200.00	0.00
7	WIRING CHECK	New	80.00	60.00
8	LABOUR FOR REMOVE & RENEW AIR CON CONDENSER ,TOP UP GAS	New	150.00	0.00
9	LABOUR FOR CHECK & RECTIFY STEREO SYSTEM	New	500.00	120.00
10	LABOUR FOR REMOVE & RENEW RADIATOR ,TOP UP COOLANT	New	150.00	60.00
11	TO APPLY RUST PROOF /TUFF COAT ON ACCIDENT AREAS	New	300.00	60.00
12	LABOUR FOR REMOVE & TRANSFER ALL REAR TAILGATE FITTING	New	300.00	40.00
Gross Labour Cost (S\$)			5,880.00	3,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >